



System Logo Program (SLP)

Intel[®] Desktop System

DP67BG

SLP Report

12/16/2010

Purpose:

This report describes the DP67BG System Logo Program testing run conducted by Intel Corporation.

THIS TEST REPORT IS PROVIDED "AS IS" WITH NO WARRANTIES WHATSOEVER, INCLUDING ANY WARRANTY OF MERCHANTABILITY, FITNESS FOR ANY PARTICULAR PURPOSE, OR ANY WARRANTY OTHERWISE ARISING OUT OF ANY PROPOSAL, SPECIFICATION OR SAMPLE.

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppels or otherwise, to any intellectual property rights is granted by this document or by the sale of Intel products. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel retains the right to make changes to its test specifications at any time, without notice.

The hardware vendor remains solely responsible for the design, sale and functionality of its product, including any liability arising from product infringement or product warranty.

Intel® Core™ i7 and Intel® are trademarks of Intel Corporation in the U.S. and other countries.

*Other names and brands may be claimed as the property of others

Copyright © 2009, Intel Corporation. All rights reserved.

Contents

- Introduction4**
 - Terms and Definitions4
- Desktop Board Configuration5**
 - Desktop Board DP67BG Final Configuration Report: Completion of SLP5
 - Board Information.....5
 - Product Code5
 - Processor.....5
 - Motherboard.....5
 - System Memory5
 - Power Management5
 - Operating System Tested.....5
 - Onboard Integrated Devices and Driver for Vista 32-bit and 64-bit.....6
 - Onboard Integrated Devices and Driver for Windows 7 32-bit and 64-bit.....7
 - Windows Logo Kits Used (WLK)8
 - Errata and Contingencies.....8
 - Test Notes 12

Introduction

Terms and Definitions

Term	Definitions
WHQL	Windows* Hardware Qualification Lab
WLK	Windows Logo Kits
SLP	System Logo Program. For further information see: http://www.microsoft.com/whdc/hwtest/default.mspx
AP Machine	Audio Precision Machine
Winqual	Windows Qualification
MSFT Tested Product List	Tested Products List. You can view the Windows Marketplace for tested products list at: http://winqual.microsoft.com/HCL/ProductList.aspx?m=v&cid=105&g=s

Desktop Board Configuration

Desktop Board DP67BG Final Configuration Report: Completion of SLP

Data in this section reflects system configuration at time of SLP submission.

Board Information

Product Code¹	BIOS String/Model	Technologies NOT Logo'd (yet)
DP67BG	BGP6710J.86A.1569.2010.1101.1220	N/A - all technologies logo'd
Processor		
Speed	3.4GHz	
Family	Intel® Sandybridge i7 2600 D2	
Bus Speed	1333 MHz	
Motherboard		
Board AA #	G10491	
Board FAB #	300	
* This report applies to the production FAB revision; Please consult your Intel Corporation representative to clarify the motherboard revision you intend to perform logo testing if not the same.		
System Memory		
Speed	Dual Channel, DDR3, 1333MHz	
Memory Type	DIMM	
Connector Type	DDR3, 240 Pin	
Power Management		
BIOS Default	S3	
Operating System Tested		
	Check Tested	Comments
Windows 7 and 64-bit	<input checked="" type="checkbox"/>	Windows 7 Ultimate
Windows 7 and 32-bit	<input checked="" type="checkbox"/>	Windows 7 Ultimate

¹ These are the product names to enter in the "Submission ID of previously logo'd qualified PC system or server" field during your "System Using a Previously Logo'd Motherboard" submission to Microsoft.

Onboard Integrated Devices and Driver for Windows 7 32-bit and 64-bit

Technology	OS	Version	Package version
Chipset Update Utility Intel® Chipset Software Utility	Windows 7	9.2.0.1015	9.2.0.1015
	Windows 7 64-bit	9.2.0.1015	9.2.0.1015
Audio Realtek ALC892/889	Windows 7	6.0.1.6194	PG310
	Windows 7 64-bit	6.0.1.6194	PG310
LAN Intel 82579V	Windows Vista	11.8.74.0	N/A
	Windows 7 64-bit	11.8.74.0	N/A
USB 3.0 NEC uPD720200	Windows 7	2.0.20.0	N/A
	Windows 7 64-bit	2.0.20.0	N/A
ME Intel CPT_1.5M	Windows 7	7.0.0.1118	N/A
	Windows 7 64-bit	7.0.0.1118	N/A
ESATA Marvell SATA	Windows 7	1.2.0.7600	N/A
	Windows 7 64-bit	1.2.0.7600	N/A
CIR Nuvoton W83677HG-I	Windows 7	2.2.2010.714	N/A
	Windows 7 64-bit	2.2.2010.714	N/A
IRST Intel P67	Windows 7	10.0.0.1046	10.0.0.1046
	Windows 7 64-bit	10.0.0.1046	10.0.0.1046

Additional Devices and Driver for Windows 7 32-bit and 64-bit

Technology	OS	Version	Package version
PCIe x16 Graphic Card Nvidia 9800GT	Windows 7	6.0.1.6194	260.99
	Windows 7 64-bit	6.0.1.6194	260.99
Wireless MSI MS-3871	Windows 7	3.1.4.0	3.1.4.0
	Windows 7 64-bit	3.1.4.0	3.1.4.0
Bluetooth MSI MS-3871	Windows Vista	3.0.2.272	N/A
	Windows 7 64-bit	11.8.74.0	N/A
PCIe x1 TV Card Hauppauge Win TV HVR-1200	Windows 7	1.44.27253.0	N/A
	Windows 7 64-bit	1.44.27253.0	N/A

Windows Logo Kits Used (WLK)

Microsoft website: <http://www.microsoft.com/whdc/DevTools/WDK/DTM.msp>

Please check regularly for test kit updates from Microsoft. Please ensure latest filters updated prior to WHQL run.

Operating Systems	Notes	WHQL Testkit
Windows 7 Windows 7 64-bit	WLK1.5 for Windows 7	WLK1.5 for Windows 7
Windows Vista Windows Vista 64-bit	WLK1.5 for Windows Vista SP2	WLK1.5 for Windows Vista SP2

Errata and Contingencies

Operating System	Failing Test	Expiry Date	ID Number	Type	Error Description
Windows 7 Windows 7 64-bit	Class Drive AC3 Test - Win7 (System)	6/30/2025	1256	Erratum	<p>Issue Description:</p> <p>Run AC3 test on a system with the Microsoft HD Audio class driver installed. Expected results: All AC3 kernel streaming data ranges should advertise MinimumBitsPerSample = 16 and MaximumBitsPerSample = 16. Actual results: HD Audio class driver sometimes advertises MaximumBitsPerSample = 24.</p> <p>Resolution Description:</p> <p>This is an acceptable failure.</p>
Windows 7 Windows 7 64-bit	1)Class Drive AC3 Test - Win7 (System) 2) Fidelity Test - Win7 (System, Manual)	1/31/2011	1801	Erratum	<p>Issue Description:</p> <p>There is a test bug which causes the measurement of system noise during Render Power Transition Test to be about 3 dB worse than it should be. This filter forgives errors up to 6 dB.</p> <p>Resolution Description:</p> <p>This is an acceptable failure.</p>
Windows 7 Windows 7 64-bit	1)Class Drive AC3 Test - Win7 (System) 2) Fidelity Test - Win7 (System, Manual)	6/1/2011	1012	Erratum	<p>Issue Description:</p> <p>Fidelity uses too small of a buffer and wakes up too infrequently during the System Activity test. This causes errors like: Noise level during system activity on (left or right) channel 73.2016 dB: *** FAIL *** (requirement >= 80 dB)</p> <p>Resolution Description:</p> <p>The signature of this failure is a lot of good-looking noise measurements during System Activity Test (noise levels down around -90 dBV) with a few sporadic bad noise measurements (-80 dB, -70 dBV) sprinkled throughout (where the glitches happen.) This filter will forgive noise level during system activity of up to -65 dB.</p>
Windows 7 64-bit	Class Drive Fidelity Test - Win7 (System, Manual)	7/31/2011	598	Erratum	<p>Issue Description:</p> <p>The European Union requires the headphone output level to be <= 150 mVrms for headphone jacks. There's a note in WLP requirement AUDIO-0006 that states, in the presence of regional</p>

					<p>regulations, the output level requirement for headphones is dropped from ≥ 1000 mVrms to ≥ 120 mVrms. This provides freedom for manufacturers to meet both the EU ≤ 150 mVrms @ 32 Ohms and the WLP ≥ 120 mVrms @ 32 Ohms requirements. The Fidelity Test tests headphones at 300 Ohm load, though. Without knowledge of the output impedance at the jack, the test cannot extrapolate what the output level at 32 Ohms would have been from the output level at 300 Ohms. The test assumes that the output level at 32 Ohms will be *less* than the output level at 300 Ohms, though. So any measurement ≥ 120 mVrms at 300 Ohms "could be" a passing result, depending on the output impedance.</p> <p>Resolution Description: This errata covers headphone output level failures where the output level ≥ 120 mVrms (-45.41 dBV.) 120 mV is -18.42 dBV. Any headphone output level at 32 Ohms that is less than -18.42 dBV is a legitimate failure, even if it is targeted at EU compliance. Any headphone output level greater than 1 Vrms (0.707 Vrms for mobile systems) is a legitimate pass, regardless of EU compliance.</p>
Windows 7 Windows 7 64-bit	PCI Hardware Compliance Test For Systems	6/1/2011	401	Erratum	<p>Issue Description:</p> <p>The following PCI Compliance test failure is acceptable: Bit 15 (Bridge Configuration Retry Enable) in the Device Control register (offset 8h) in the PCI Express Capability table must be read-only and always return 0 as it is reserved for devices other than PCI Express to PCI/PCI-X Bridges. Assertion 13A41D3E-2576-41DC-A67C-525DA3637CEA This failure is acceptable because this is a PCIe 1.1 feature and the WLP requires compliance with only PCIe 1.0a.</p>
Windows 7 Windows 7 64-bit	PCI Hardware Compliance Test For Systems	6/1/2011	923	Erratum	<p>Issue Description:</p> <p>Assertion FAE18121-9177-4FB2-A081-0D04C285EFF2 Bit range 15:0 (Extended Capability ID) in the Enhanced Capability Header register (offset 0h) in the Unrecognized Enhanced Capability ID 13 table is Dh. It must be in the range [0x0 - 0xB] as all other Capability IDs are reserved.</p> <p>Resolution Description:</p> <p>This erratum is in place because the PCI Compliance test doesn't recognize Extended Capability IDs greater than 0xB. The PCI Compliance test will be updated to correct this in the future.</p>
Windows 7 Windows 7 64-bit	PCI Hardware Compliance Test For Systems	6/1/2011	1241	Erratum	<p>Issue Description:</p> <p>This happens because the PCI Compliance test assumes that if the Data Link Layer Link Active Reporting Capable bit in the Link Capabilities</p>

					<p>register for a given PCIe port is set then that indicates that the Data Link Layer Link Active bit will also be set. This is an incorrect assumption because the Data Link Layer Link Active bit can be reset when there is no device below the port. This assertion needs to be removed from the PCIHCT. The current architecture of the PCIHCT prevents it from knowing whether devices exist below a bridge/port.</p> <p>Resolution Description:</p> <p>This is an acceptable failure: Assertion 0E36472A-0EDB-4685-A67D-7AF1FFBFA81B Data Link Layer Link Active Reporting Capable bit is set but Data Link Layer Link Active is not.</p>
Windows 7 Windows7 64 bit	UAA Test - Vista or Server08 (System)	2/28/2011	1299	Erratum	<p>Issue Description:</p> <p>Preview filter - Jack Detect Override on digital pin widgets Errata 1299 The HD Audio configuration default register (7.3.3.31 in the HD Audio specification) includes a "Jack Detect Override" flag that can be used to indicate that although a pin widget would normally be capable of jack detection, there is something about this particular system that causes this to be impossible. This was intended to be used, for example, for analog pin widgets that are connected to RCA jacks, which do not allow for impedance detection. Some digital pin widgets are using the Presence Detect pin sense response to indicate that a digital handshake has occurred - indeed, HDMI pins have entire DCNs built around this concept, and it applies equally well to S/PDIF pins. A digital converter that supports presence detection should be able to do so in any system, so the "Jack Detect Override" concept should not apply to digital pins.</p> <p>Resolution Description:</p> <p>When this Errata expires, the issue described will be considered a valid failure.</p>
Windows 7 Windows7 64 bit	UAA Test - Vista or Server08 (System)	6/1/2011	1300	Erratum	<p>Issue Description:</p> <p>HD Audio pin configuration document calls out setting Port Connectivity to No Connection as the way to turn a pin off in a particular system. UAA Test incorrectly tests such pins.</p> <p>Resolution Description:</p> <p>This is an acceptable failure.</p>
Windows 7 Windows7 64 bit	UAA Test - Vista or Server08 (System)	6/1/2015	513	Erratum	<p>Issue Description:</p> <p>UAA Test requires the Traffic Priority bit to be read/write - however there are two specs that apply, and they conflict. One says the bit must be read/write, the other says it must be read-only. Contact has been made with the author of both specs (Intel) but until this point is clarified we cannot fail submissions containing this test failure.</p>
Windows 7 Windows7 64 bit	USB Host Controller Compliance (Automated)	6/1/2012	1787	Erratum	<p>Issue Description:</p> <p>Errata 1787 This Preview Test is being filtered until the expiration date of this Errata. After the</p>

				<p>expiration date of this filter these failures must be fixed to have a passing submission. Microsoft strongly recommends that these errors be investigated prior to this test or job being required for submission. XHCI spec compliance test is in preview</p>
--	--	--	--	---

Resolution Description:

XHCI spec compliance test is in preview For further details visit:
<https://winqual.microsoft.com/ec/>

Test Notes

Operating System	Test	Description
Windows 7 and Vista	BIOS download	Internal: http://bios.intel.com/downloads/ External: http://www.intel.com/ click on Support and Download
Windows 7 and Vista	BIOS setup	Please make sure the BIOS setting are as below, otherwise use default settings. System Date and Time: Current date and time Enhance customer IR: Enable Boot Device Priority: set <Hard Disk Driver> to first Others: BIOS default setting
Windows 7 and Vista filter update	WLK WHQL test	http://winqual.microsoft.com/member/SubmissionWizard/LegalExemptions/filterupdates.cab
Special H/W that use to PASS the test	None	None