



# Monthly Specification Update

**Intel® Server Board S1400FP Family**  
**Intel® Server System P4000FP Family**



July, 2012

Enterprise Platforms and Services Marketing



## Revision History

Date	Modifications
July, 2012	Initial release.

## Disclaimers

This Monthly Specification Update of the Server System may contain design defects or errors known as errata that may cause the product to deviate from the published specifications. Current characterized errata are documented in this Specification Update.

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, lifesaving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Intel, Itanium, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation.

\*Other brands and names may be claimed as the property of others.

Copyright © Intel Corporation 2012.

# Contents

<b>Preface</b> .....	<b>1</b>
1.    Nomenclature.....	1
2.    Product Scope.....	1
<b>Summary Tables of Changes</b> .....	<b>2</b>
<b>Errata</b> .....	<b>4</b>
1.    Linux* Operating Systems are not supported on RSTe mode.....	4
2.    UEFI Microsoft Windows Server 2008* R2 SP1 installation on SCU ports may fail under RSTe RAID mode .....	4
3.    UEFI Operating System installation is not supported on ESRT2 mode.....	4
4.    HDD status LEDs do not function under specific configuration .....	5
5.    RSTe GUI installation may fail if there are no devices attached to any onboard AHCI ports .....	5
6.    System may halt under specific BIOS configurations.....	5
7.    Microsoft Windows 2003* x86 installation failure under Pass-through mode of SCU controller .....	5
8.    System may halt under unsupported configuration in ESRT2 mode .....	6
9.    Integrated BMC Web Console – Power Statistics page – Minimum wattage reads as zero .....	6
10.   Integrated BMC Web Console – Power Control page – Perform Action button not functional .....	6
11.   IPMI Get Chassis Status command returns incorrect Chassis Identify State. ....	7
12.   The BIOS and ME Firmware can't be updated successfully using Intel® One Boot Flash Update Utility(OFU) under SuSE* Linux Enterprise Server 11 (64-bit) with SP2.....	7
13.   BMC continuously sends HDD assert/de-assert event during HDD RAID rebuild under ESRT2 mode of the SCU controller .....	7
14.   High CPU utilization may occur when installing or running Microsoft Windows Server 2008* R2 or Microsoft Windows* 7 with default NIC driver for Intel® Gigabit ET Dual Port Server Adapter E1G42ET and Intel® Gigabit ET Quad Port Server Adapter E1G44ET.....	8
15.   Intel® LAN driver installation failure on Microsoft Windows* 7.....	8
16.   Hard drives connected through SAS expander can't be detected in legacy mode ..	8
17.   On-board VGA cannot be set to the highest resolution (1920x1080 and higher) ....	9
18.   Hard drive locate LED may not instantly respond to the locate command if backplane is connected through SAS expander to a RAID controller .....	9
19.   Some log names in SEL are displayed incorrectly after pressing the power button to shut down Microsoft Windows 2008* R2 64bit .....	9
20.   Fault LED on 4x3.5” hot swap HDD cage may not function normally during RAID rebuilding with AHCI ESRTII RAID configuration .....	10
21.   Integrated BMC Web Console – Sensor Readings Page – Memory Throttling sensor status will stay “Critical” once triggered .....	10
22.   WOL (Wake on LAN) may not function under Red Hat* Linux 6.2 64bit OS .....	10
<b>Documentation Changes</b> .....	<b>11</b>

<This page is intentionally left blank.>

# Preface

---

This document is an update to the specifications contained in the *Intel® Server Board S1400FP Family and Intel® Server System P4000FP Family Technical Product Specification*. It is intended for hardware system manufacturers and software developers of applications, operating systems, or tools. It will contain specification changes, specification clarifications, errata, and document changes.

## 1. Nomenclature

- **Specification Changes** are modifications to the current published specifications for Intel® server boards. These changes will be incorporated in the next release of the specifications.
- **Specification Clarifications** describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in the next release of the specifications.
- **Documentation Changes** include typos, errors, or omissions from the current published specifications. These changes will be incorporated in the next release of the specifications.
- **Errata** are design defects or errors. Errata may cause the server board behavior to deviate from published specifications. Hardware and software designed to be used with any given processor stepping must assume that all errata documented for that processor stepping are present on all devices.

## 2. Product Scope

The following specific boards, BIOS and components are covered by this update:

Product Code	Baseboard PBA Revision	BIOS Revision	BMC Revision	FRU/SDR Revision	ME Revision
S1400FP2	G51107-203	01.03.0002	01.10.3560	D.03	02.01.05.107
S1400FP4	G49708-203	01.03.0002	01.10.3560	D.03	02.01.05.107

## Summary Tables of Changes

---

The following tables provide an overview of known errata and known document changes that apply to the specified Intel Server Products. The tables use the following notations:

**Doc:** Intel intends to update the appropriate documentation in a future revision.

**Fix:** Intel intends to fix this erratum in the future.

**Fixed:** This erratum has been previously fixed.

**No Fix:** There are no plans to fix this erratum.

**Shaded:** This erratum is either new or has been modified from the previous specification update.

**Table 1. Errata Summary**

No.	Plans	Description of Errata
1.	Fix	Linux* Operating Systems are not supported on RSTe mode
2.	Fix	UEFI Microsoft Windows Server 2008* R2 SP1 installation on SCU ports may fail under RSTe RAID mode
3.	Fix	UEFI Operating System installation is not supported on ESRT2 mode
4.	Fix	HDD status LEDs do not function under specific configuration
5.	Fix	RSTe GUI installation may fail if there are no devices attached to any onboard AHCI ports
6.	Fix	System may halt under specific BIOS configurations
7.	Fix	Microsoft Windows 2003* x86 installation failure under Pass-through mode of SCU controller
8.	Fix	System may halt under unsupported configuration in ESRT2 mode
9.	Fix	Integrated BMC Web Console – Power Statistics page – Minimum wattage reads as zero.
10.	Fix	Integrated BMC Web Console – Power Control page – Perform Action button not functional.
11.	Fix	IPMI Get Chassis Status command returns incorrect Chassis Identify State.
12.	Fix	The BIOS and ME Firmware can't be updated successfully using Intel® One Boot Flash Update Utility (OFU) under SuSE* Linux Enterprise Server 11 (64-bit) with SP2
13.	Fix	BMC continuously sends HDD assert/de-assert event during HDD RAID rebuild under ESRT2 mode of the SCU controller
14.	Fix	High CPU utilization may occur when installing or running Microsoft Windows Server 2008* R2 or Microsoft Windows* 7 with default NIC driver for Intel® Gigabit ET Dual Port Server Adapter E1G42ET and Intel® Gigabit ET Quad Port Server Adapter E1G44ET
15.	Fixed	Intel® LAN driver installation failure on Microsoft Windows* 7
16.	Fix	Hard drives connected through SAS expander can't be detected in legacy mode
17.	Fix	On-board VGA cannot be set to the highest resolution (1920x1080 and higher)
18.	Fix	Hard drive locate LED may not instantly respond to the locate command if backplane is connected through SAS expander to a RAID controller
19.	Fix	Some log names in SEL are displayed incorrectly after pressing the power button to shut down Microsoft Windows 2008* R2 64bit
20.	Fix	Fault LED on 4x3.5" hot swap HDD cage may not function normally during RAID rebuilding with AHCI ESRTII RAID configuration
21.	Fix	Integrated BMC Web Console – Sensor Readings Page – Memory Throttling sensor status will stay "Critical" once triggered

No.	Plans	Description of Errata
22.	Fix	WOL (Wake on LAN) may not function under Red Hat* Linux 6.2 64bit OS

**Table 2. Documentation Changes**

No.	Plans	Document Name	Description of Documentation Change
1.			

The following sections provide in-depth descriptions of each erratum/documentation change indicated in the tables above. The errata and documentation change numbers referenced in the following sections correspond to the numbers in the tables above.

## Errata

---

### 1. Linux\* Operating Systems are not supported on RSTe mode

Problem	Intel® RSTe mode is not supported on Red Hat* Linux and SUSE* Linux.
Implication	User may not able to install Red Hat* Linux and SUSE* Linux on Intel® C600 Series Chipset based Server Boards under Intel® RSTe mode.
Status	This issue may be fixed in future driver or BIOS releases.
Workaround	None.

### 2. UEFI Microsoft Windows Server 2008\* R2 SP1 installation on SCU ports may fail under RSTe RAID mode

Problem	System may encounter blue screen when installing Microsoft Windows Sever 2008* R2 SP1 under UEFI with below configurations: <ol style="list-style-type: none"><li>1. Intel® C600 RAID Upgrade Key is installed and SAS HDDs are used on SCU ports.</li><li>2. BIOS options “EFI Optimized Boot” and “Use Legacy Video for EFI OS” are enabled.</li><li>3. Under RSTe RAID mode.</li></ol>
Implication	User may not able to install UEFI Microsoft Windows Server 2008* R2 SP1 on Intel® C600 Series Chipset based Server Boards with mentioned configuration.
Status	This issue may be fixed in a future BIOS release.
Workaround	None.

### 3. UEFI Operating System installation is not supported on ESRT2 mode

Problem	UEFI OS installation of Microsoft Windows*, Red Hat* Linux or SUSE* Linux may fail on AHCI or SCU controller when “EFI Optimized Boot” and “Use Legacy Video for EFI OS” are both enabled.
Implication	User may not be able to install UEFI OS under ESRT2 mode on Intel® C600 Series Chipset based Server Boards.
Status	This issue may be fixed in a future BIOS revision.
Workaround	None.



#### 4. HDD status LEDs do not function under specific configuration

Problem	If drives are connected through expander to SCU ports and configured under RSTe mode, the HDD status LEDs may not function properly.
Implication	HDD status LED may not show the HDD locate, HDD fault or RAID rebuild message.
Status	This issue may be fixed in a future RAID driver.
Workaround	None.

#### 5. RSTe GUI installation may fail if there are no devices attached to any onboard AHCI ports

Problem	When Microsoft Windows 2008* R2 is installed on SCU ports, the installation of RSTe drivers and the Graphic User Interface (GUI) in Microsoft Windows 2008* R2 will fail, if the AHCI controller is enabled while no device is attached to the AHCI SATA ports.
Implication	User may not be able to install RSTe GUI under mentioned configuration when the AHCI controller is enabled and no devices are attached to the AHCI SATA ports.
Status	This issue may be fixed in a future RAID driver.
Workaround	The workaround is to either plug a SATA device into one of the AHCI SATA ports, or disable the onboard AHCI controller in BIOS.

#### 6. System may halt under specific BIOS configurations

Problem	Once BIOS options “EFI Optimized Boot” and “Memory Mapped I/O Above 4GB” are both enabled, and RSTe mode is selected, system may halt during the system POST.
Implication	User may see system hang with mentioned configuration.
Status	This issue may be fixed in a future RSTe UEFI driver release.
Workaround	None.

#### 7. Microsoft Windows 2003\* x86 installation failure under Pass-through mode of SCU controller

Problem	Microsoft Windows Server 2003* x86 installations on SCU RSTe pass-through mode fail.
---------	--

Implication	User may not able to install Microsoft Windows Server 2003* x86 on mentined BIOS configuration.
Status	This issue may be fixed in a future RSTe driver release.
Workaround	None.

## 8. System may halt under unsupported configuration in ESRT2 mode

Problem	If no Intel® C600 RAID upgrade key (any of RKSAS4, RKSAS4R5, RKSAS8, RKSAS8R5) is installed to enable SAS support capablity under ESRT2 mode while SAS drivers are used, the system may halt at the boot stage.
Implication	User may see a system halt with no RAID keys installed with SAS drivers used and ESRT2 enabled.
Status	This issue may be fixed in a future BIOS release.
Workaround	None.

## 9. Integrated BMC Web Console – Power Statistics page – Minimum wattage reads as zero.

Problem	On some systems the Integrated BMC Web Console Power Statistic page may display the minimun wattage as zero (0W) after the system has been powered. This reading will stay at zero until the next power cycle of the system.
Implication	This is an incorrect reading only and does not affect operation.
Status	This issue may be fixed in a future BMC release.
Workaround	None.

## 10. Integrated BMC Web Console – Power Control page – Perform Action button not functional.

Problem	After performing a Graceful shutdown from the Integrated BMC Web Console Power Control page the Perform Action button gets grayed out and cannot be pressed to request another action.
Implication	You cannot perform a power on of the system.
Status	This issue may be fixed in a future BMC release.
Workaround	Select another page in the Integrated BMC Web Console and then return to the Power Control Page. The Perform Action button will then be available.

## 11. IPMI Get Chassis Status command returns incorrect Chassis Identify State.

Problem	When a Get Chassis Status command is issued, after the Chassis Identify LED has been forced on, the status of off (00b) is returned for Chassis Identify State (response data byte 4 – bits [5:4]).
Implication	Unable to correctly read when the Chassis Identify LED is on.
Status	This issue may be fixed in a future BMC release.
Workaround	None.

## 12. The BIOS and ME Firmware can't be updated successfully using Intel® One Boot Flash Update Utility (OFU) under SuSE\* Linux Enterprise Server 11 (64-bit) with SP2

Problem	OFU will fail to update BIOS & ME under SuSE* Linux Enterprise Server 11 (64-bit) with SP2 Operating System.
Implication	If the system is running SuSE* Linux Enterprise Server 11 (64-bit) with SP2 Operating System, using OFU to update System Firmware Update Package(SFUP) will fail.
Status	This issue may be fixed in a future OFU version.
Workaround	Update System Firmware Update Package(SFUP) from EFI environment using iFlash32, FWPIAUpdate and FRUSDR Utility.

## 13. BMC continuously sends HDD assert/de-assert event during HDD RAID rebuild under ESRT2 mode of the SCU controller

Problem	HDD fault will keep asserting and de-asserting frequent during RAID rebuild under ESRT2.
Implication	During HDD ESRT2 RAID rebuild, there's flood HDD fault assert/deassert (SAS RAID) or Rebuild/remap (SATA RAID) logs into SEL.
Status	This issue may be fixed in a future BIOS release.
Workaround	None.

## 14. High CPU utilization may occur when installing or running Microsoft Windows Server 2008\* R2 or Microsoft Windows\* 7 with default NIC driver for Intel® Gigabit ET Dual Port Server Adapter E1G42ET and Intel® Gigabit ET Quad Port Server Adapter E1G44ET

Problem	There has been high CPU load observed when installing or running Microsoft Windows Server 2008* R2 or Microsoft Windows 7* with default NIC (Network Interface Card) driver for Intel® Gigabit ET Dual Port Server Adapter E1G42ET and Intel® Gigabit ET Quad Port Server Adapter E1G44ET.
Implication	When the ports are not electrically "linked" and the embedded driver is loaded, the DPC rate steadily increases until the system slows to the point where it is essentially unusable.
Status	This issue may be fixed in a future driver release.
Workaround	None.

## 15. Intel® LAN driver installation failure on Microsoft Windows\* 7

Problem	The Intel® LAN driver version 16.8 and below may not be installed successfully on Microsoft Windows 7* with the .bat installation scripts in the driver package.
Implication	The LAN driver can not be installed by the .bat installation scripts in the driver package.
Status	The issue is fixed in Intel® LAN driver version 17.1
Workaround	Two workarounds are available: <ol style="list-style-type: none"><li>1. The LAN driver can be manually installed.</li><li>2. User can lower the "User Account Control" to "Never Notify", then the driver can be installed with the .bat installation scripts.</li></ol>

## 16. Hard drives connected through SAS expander can't be detected in legacy mode

Problem	If hard drives are connected through expander to SCU ports and configured under RSTe mode, the hard drives can't be detected by system in legacy mode (default BIOS setting).
Implication	Users can't use the hard drives connected through expander as boot device to install OS. But users can install OS to other hard drives which are not connected through expander and load RSTe driver to make the hard drives connected through expander visible to OS. Or users can change Boot Options > EFI Optimized Boot to "Enabled" in BIOS Setup so that hard drives connected through expander can be detected by the system.

Status This issue may be fixed in a future BIOS release.

Workaround None.

## 17. On-board VGA cannot be set to the highest resolution (1920x1080 and higher)

Problem The Graphics ID register in the on-board video controller is getting set incorrectly.

Implication The video cannot be set to the highest resolutions listed here:

[1920x1080,High 256 Color, 60 Hertz]  
[1920x1200,High 256 Color, 60 Hertz]  
[1920x1080,High Color(16bit), 60 Hertz]  
[1920x1200,High Color(16bit), 60 Hertz]

Status This issue may be fixed in a future BMC release.

Workaround None

## 18. Hard drive locate LED may not instantly respond to the locate command if backplane is connected through SAS expander to a RAID controller

Problem If backplane is connected through SAS expander to a RAID controller, the hard drive locate LED may not instantly respond to the locate command from the RAID controller. The LED may blink after up to 2 minutes.

Implication The symptom doesn't happen if backplane is directly connected to the RAID controller. Root cause has been identified in the motherboard BMC.

Status This issue may be fixed in a future BMC release.

Workaround None.

## 19. Some log names in SEL are displayed incorrectly after pressing the power button to shut down Microsoft Windows 2008\* R2 64bit

Problem If pressing power button to shut down Microsoft Windows 2008\* R2 64bit, some SEL log names are displayed as "unknown" or "N/A".

Implication No function impact to system, only some redundant SEL logs.

Status This issue may be fixed in a future BMC release.

Workaround None.

## 20. Fault LED on 4x3.5" hot swap HDD cage may not function normally during RAID rebuilding with AHCI ESRTII RAID configuration

Problem	If system is configured as AHCI ESRTII RAID, HDD Fault LED may display "Off" during RAID HDD rebuilding.
Implication	You may observe HDD Fault LED steady off during rebuilding. No function impact.
Status	This issue may be fixed in a future ESRTII driver release.
Workaround	None.

## 21. Integrated BMC Web Console - Sensor Readings Page - Memory Throttling sensor status will stay "Critical" once triggered

Problem	When Memory Throttling is triggered, the Memory "P1 MTT and/or P2 MTT" sensor status will stay at "Critical" status in the Integrated BMC Web Console even after throttling has stopped.
Implication	You may observe Memory "P1 MTT and/or P2 MTT" status as "Critical" even when there is no throttling. No functional impact to the system.
Status	This issue may be fixed in a future ME release.
Workaround	Need a AC cycle or reset ME through IPMI to reset the MTT sensor status.

## 22. WOL (Wake on LAN) may not function under Red Hat\* Linux 6.2 64bit OS

Problem	With Intel® LAN driver version 17.1, WOL (Wake on LAN) may not function under Red Hat* Linux 6.2 64bit OS.
Implication	You may not be able to wake system through onboard NIC port.
Status	This issue may be fixed in a future LAN driver release.
Workaround	None.

## Documentation Changes

---

N/A