



# **Intel<sup>®</sup> Server Boards S5000PSL and S5000XSL**

## ***Specification Update***

*Intel Order Number D62900-001*

**September 2009**

**Enterprise Platforms and Services Marketing**

---

## Revision History

Date	Modifications
05/20/06	Initial release. Added errata 1 through 24.
07/13/06	Added errata 25 and 26.
08/15/06	Added errata 27 through 30.
02/14/07	Added erratum 31.
04/18/07	Added erratum 32.
09/14/07	Updated erratum 14, 21, 29, 30, and 31. Added erratum 33 through 48.
01/11/08	Updated erratum 23, 45 through 48. Added erratum 49.
07/28/08	Updated erratum 15,20,22,24, and 49. Added erratum 50 through 52.
10/23/08	Updated erratum 51. Added erratum 53.
12/07/08	Updated product scope and erratum 50 and 53. Added erratum 54.
01/09/08	Added erratum 55.
02/11/2009	Updated erratum 54.
03/18/2009	No update.
04/09/2009	No update.
05/12/2009	No update.
07/14/2009	Added erratum 56.
09/15/2009	Added erratum 57.

## ***Disclaimers***

The Intel® Server Boards S5000PSL and S5000XSL may contain design defects or errors known as errata that may cause the product to deviate from the published specifications. Current characterized errata are documented in this Specification Update.

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Intel, Itanium, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation.

\*Other brands and names may be claimed as the property of others.

Copyright © Intel Corporation 2007-2009.

# Contents

<b>Preface</b> .....	<b>1</b>
<b>Summary Tables of Changes</b> .....	<b>5</b>
<b>Errata</b> .....	<b>8</b>
1. Console Redirection baud rate setting auto changing to 19.2K with Serial Over LAN (SOL) active	8
2. Serial Over LAN (SOL) unable to redirect DOS output.....	8
3. Password on boot not supported .....	8
4. SAS Software RAID option is not enabled in the initial BIOS release. ....	9
5. Secondary HSC backplane FW not visible in the BIOS setup.....	9
6. Removed as Duplicate.....	9
7. HSC and BMC versions intermittently not seen in the BIOS setup .....	10
8. POST LEDs do not turn off after Operating System loads .....	10
9. Checkup7.exe (microcode update utility) is not storing microcode in the BIOS .....	10
10. Intel® Server RAID Card SRCSAS144E causes systems to reset multiple times before completing POST.....	11
11. Change Logo utility does not save modified BIOS capsule files with correct extension....	11
12. IPMI over Serial direct connect not supported.....	11
13. Serial over LAN and IPMI over LAN connections may terminate unexpectedly under certain conditions.....	12
14. Intermittent beep code 1-5-2-1 when booting with dual processors .....	12
15. Power Supply population errors may not appear in SEL .....	12
16. Fan 5 may report a reading of 0 RPM after BMC is updated.....	13
17. BMC may not respond to the IPMI command, <i>Send Message</i> sent via LAN .....	13
18. Fans may take a long time to slow down after fan boosting .....	13
19. System requires approximately 35 seconds after AC power applied before power button responds	14
20. SEL events for HSC may appear after DC cycle .....	14
21. Fans may run faster than expected after exiting BIOS setup .....	14
22. System fault LED may report incorrect status for some events.....	14
23. Fan removal does not generate SEL event .....	15
24. Power supply redundancy state is misleading when only one power supply is installed...	15
25. PCI-X slots 1 and 2 do not meet the letter of the Server System Infrastructure (SSI) Entry-level Electronics Bay (EEB) Specification revision 3.61 .....	15

26. Serial ATA (SATA) HDDs may be marked offline when populated behind a second Serial Attached SCSI (SAS) expander based drive enclosure .....	16
27. Failures seen installing to a SATA drive when SATA is set to Legacy in BIOS setup.....	16
28. System Hangs after disabling Onboard Video in BIOS setup.....	16
29. The SMBIOS entry point may not be visible under certain hardware configurations.....	17
30. Fans occasionally running too fast after BIOS reset.....	17
31. SAS SW RAID option is erroneously available in BIOS setup after loading optimal default settings on the S5000PSLROMB server board .....	18
32. RAID Web Console 2 Utility Displays “Unexpected Sensor” Warning Message in Microsoft Windows* Operating System .....	18
33. PS/2 keyboards and mice may stop functioning after Red Hat* Enterprise Linux is installed	19
34. HSC and LCP updates may take a long time .....	19
35. SuSE* Linux Enterprise Server may not install successfully with Intel® Embedded Server RAID Technology II enabled.....	19
36. Red Hat* Enterprise Linux 4 and BIOS setup display a different L2 cache size for the Intel® Xeon® Processor 5300 Series.....	20
37. Change Logo Utility causes BIOS corruption .....	20
38. Microsoft Windows* System Event Viewer may record ID 11 Error Event .....	20
39. POST screen may generate “NMI has been received – System Halted” message after the system reboots .....	21
40. S5000PSLSAS software RAID 5 cannot be configured.....	21
41. SuSE* Linux Enterprise Server unable to boot after basic installation .....	21
42. Red Hat* Enterprise Linux may report the wrong processor speed.....	22
43. A kernel panic is likely to be observed with Red Hat* Enterprise Linux 4 or SuSE* Linux Enterprise Server 9 when SpeedStep is disabled in BIOS menu .....	22
44. SAS software RAID 5 activation key may NOT be detected .....	22
45. Microsoft Windows* operating systems without service pack will exhibit blue screen with BIOS 79 and 81 .....	23
46. Fails PXE boot from on-board NIC 2 and neither on-board NIC works under DOS with BIOS R0079 and R0081 .....	24
47. Intel® Embedded Server RAID Technology II SAS RAID 5 consistence check fails in BIOS console only if hard drives are docked in expander HSBP.....	24
48. Sluggish system performance may be experienced with BMC60.....	24
49. Microsoft Windows Server 2003* R2 SP2 may exhibit a blue screen during an operating system boot or shutdown with a specific version of I/OAT driver .....	25
50. Recent Intel® Server RAID Adapters fail to activate RAID BIOS Console by Ctrl+G in S5000PSL and/or S5000XVN PCI slot 4.....	25
51. Microsoft Windows* Server 2008 and/or Microsoft Windows Vista* may report Performance Power Management error .....	26

52. 'Fdisk' command under Red Hat\* Enterprise Linux Server 5 Update 1 may report an Intel® Embedded Server RAID Technology II RAID 1 array as two hard disk drives ..... 27

53. Platform Confidence Test (PCT) may fail with BIOS 89 and later version loaded ..... 27

54. BIOS 94 does not support mixed stepping E-0 and C-0 processors ..... 27

55. S5000PSL/S5000XSL cannot boot from SATA CD/DVD ROM using a "bootable" Microsoft\* DOS CD/DVD when RAID (or AHCI) is Enabled in the BIOS setup ..... 28

56. System may not boot after multiple DC power cycles with BIOS revision R0098 ..... 28

57. System will not skip CD/DVD drive with BIOS revision R0098 when RMM2 installed..... 28

**This page intentionally left blank**





## Preface

---

This document is an update to the specifications contained in the *Intel® Server Boards S5000PSL and S5000XSL Technical Product Specification (D41763)*. It is intended for hardware system manufacturers and software developers of applications, operating systems, or tools. It contains specification changes, specification clarifications, errata, and document changes.

For specification updates concerning the Intel® Xeon® processor 5000 Series, refer to the *Intel® Xeon® Processor 5000 Series Specification Update (Order Number 313065)*. Items contained in the *Intel® Xeon® Processor 5000 Series Specification Update* that either do not apply to the Intel® Server Boards S5000PSL and S5000XSL or were worked around are noted in this document. Otherwise, you can assume any processor errata for a given stepping are applicable to the Printed Board Assembly (PBA) revisions(s) associated with that stepping.

For specification updates concerning the Intel® Xeon® processor 5100 Series, refer to the *Intel® Xeon® Processor 5100 Series Specification Update (Order Number 313356)*. Items contained in the *Intel® Xeon® Processor 5100 Series Specification Update* that either do not apply to the Intel® Server Boards S5000PSL and S5000XSL or were worked around are noted in this document. Otherwise, you can assume any processor errata for a given stepping are applicable to the Printed Board Assembly (PBA) revisions(s) associated with that stepping.

For specification updates concerning the *Intel® 5000 Series Chipset Memory Controller Hub (MCH)*, refer to the *Intel® 5000 Series Chipset Memory Controller Hub (MCH) Specification Update (Order Number 313069)*. Items contained in the *Intel® 5000 Series Chipset Memory Controller Hub (MCH) Specification Update* that either do not apply to the Intel® Server Boards S5000PSL and S5000XSL or were worked around are noted in this document. Otherwise, you can assume any chipset errata for a given stepping are applicable to the Printed Board Assembly (PBA) revisions(s) associated with that stepping.

For specification updates concerning the Intel® 631xESB/632xESB I/O Controller Hub, refer to the *Intel® 631xESB/632xESB I/O Controller Hub - Specification Update (Order Number 313075)*. Items contained in the *Intel® 631xESB/632xESB I/O Controller Hub - Specification Update* that either do not apply to the Intel® Server Boards S5000PSL and S5000XSL or were worked around are noted in this document. Otherwise, you can assume any chipset errata for a given stepping are applicable to the Printed Board Assembly (PBA) revisions(s) associated with that stepping.

## Nomenclature

- **Specification Changes** are modifications to the current published specifications for Intel® server boards. These changes will be incorporated in the next release of the specifications.
- **Specification Clarifications** describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in the next release of the specifications.

- **Documentation Changes** include typos, errors, or omissions from the current published specifications. These changes will be incorporated in the next release of the specifications.
- **Errata** are design defects or errors. Errata may cause the server board behavior to deviate from published specifications. Hardware and software designed to be used with any given processor stepping must assume all errata documented for that processor stepping are present on all devices.

## Product Scope

The following table is a list of the specific boards, BIOS, and components covered by this update.

Product Code	Baseboard PBA Revision	BIOS Revision	BMC Revision	FRU / SDR Revision
S5000PSLSATA	D44771-720	S5000.86B.01.00.0039	42	25
S5000PSLSATA	D44771-720	S5000.86B.01.00.0045	46	31
S5000PSLSATA	D44771-721	S5000.86B.02.00.0054	48	33
S5000PSLSATA	D44771-801	S5000.86B.03.00.0056	48a	33
S5000PSLSATA	D44771-803	S5000.86B.03.00.0059	48a	33a
S5000PSLSATA	D44771-804	S5000.86B.05.00.0070	56	41
S5000PSLSATA	D44771-805	S5000.86B.07.00.0079	59	42
S5000PSLSATA	D44771-805	S5000.86B.10.00.0081	59	43
S5000PSLSATAR	E11027-101	S5000.86B.10.00.0084	62	43
S5000PSLSATAR	E11027-102	S5000.86B.10.00.0084	62	43
S5000PSLSAS	D44749-720	S5000.86B.01.00.0054	48	33
S5000PSLSAS	D44749-801	S5000.86B.03.00.0056	48a	33
S5000PSLSAS	D44749-803	S5000.86B.03.00.0059	48a	33a
S5000PSLSAS	D44749-804	S5000.86B.05.00.0070	56	41
S5000PSLSAS	D44749-805	S5000.86B.07.00.0079	59	42
S5000PSLSAS	D44749-805	S5000.86B.10.00.0081	59	43
S5000PSLSASR	E11025-101	S5000.86B.10.00.0081	59	43
S5000PSLSASR	E11025-102	S5000.86B.10.00.0084	62	45
S5000PSLROMB	D44771-721	S5000.86B.01.00.0054	48	33
S5000PSLROMB	D44771-801	S5000.86B.03.00.0056	48a	33
S5000PSLROMB	D44771-803	S5000.86B.03.00.0059	48a	33a
S5000PSLROMB	D44771-804	S5000.86B.05.00.0070	56	41
S5000PSLROMB	D44771-805	S5000.86B.07.00.0079	59	42
S5000PSLROMB	D44771-805	S5000.86B.10.00.0081	59	43
S5000PSLROMBR	E11027-101	S5000.86B.10.00.0081	59	43
S5000PSLROMBR	E11027-102	S5000.86B.10.00.0084	62	45
BB5000XSLSATA	D16310-721	S5000.86B.01.00.0054	48	33
BB5000XSLSATA	D16310-723	S5000.86B.03.00.0056	48a	33
BB5000XSLSATA	D16310-801	S5000.86B.03.00.0059	48a	33a
BB5000XSLSATA	D16310-803	S5000.86B.03.00.0059	48a	33a
BB5000XSLSATA	D16310-804	S5000.86B.05.00.0070	56	41
BB5000XSLSATA	D16310-805	S5000.86B.07.00.0079	59	42
BB5000XSLSATA	D16310-805	S5000.86B.10T.00.0081	59	43
BB5000XSLSATAR	E11032-101	S5000.86B.10.00.0081	59	43
BB5000XSLSATAR	E11032-102	S5000.86B.10.00.0085	62	45
BB5000PSLSATAR	E11027-301	S5000.86B.10.00.0085	64	46
BB5000PSLROMBR	E11027-301	S5000.86B.10.00.0085	64	46

BB500PSLSASR	E11025-301	S5000.86B.10.00.0085	64	46
BB500XLSATAR	E11032-201	S5000.86B.10.00.0085	64	46
S5000PSLSATAR	E11027-301	S5000.86B.10.00.0085	64	46
S5000PSLSASR	E11025-301	S5000.86B.10.00.0085	64	46
S5000PSLROMBR	E11027-301	S5000.86B.10.00.0085	64	46

## Summary Tables of Changes

---

The following tables indicate the errata and the document changes that apply to the Intel® Server Boards S5000PSL and S5000XSL. Intel intends to fix some of the errata in a future stepping of components and to account for the other outstanding issues through documentation or specification changes as noted. The tables use the following notations:

**Doc:** Intel intends to update the appropriate documentation in a future revision.

**Fix:** Intel intends to fix this erratum in a future release of the component.

**Fixed:** This erratum was previously fixed.

**No Fix:** There are no plans to fix this erratum.

**Shaded:** This erratum is either new or was modified from the previous specification update.

**Table 1. Errata Summary**

No.	Plans	Description of Errata
1.	Fixed	Console Redirection Baud Rate Setting auto changing to 19.2K with Serial Over LAN (SOL) active.
2.	Fixed	Serial Over LAN (SOL) unable to redirect DOS output.
3.	No Fix	Password on boot not supported.
4.	Fixed	SAS Software RAID option is not enabled in the initial BIOS release.
5.	Fixed	Secondary HSC backplane FW not visible in the BIOS setup.
6.	Fixed	Secondary HSC backplane FW not visible in the BIOS setup.
7.	Fixed	HSC and BMC versions intermittently not seen in the BIOS setup.
8.	Fixed	POST LEDs do not turn off after operating system loads.
9.	Fixed	Checkup7.exe (microcode update utility) is not storing microcode in the BIOS.
10.	Fixed	Intel® Server RAID Card SRCAS144E causes systems to reset multiple times before completing POST.
11.	Fixed	Change Logo utility does not save modified BIOS capsule files with correct extension.
12.	Fix	IPMI over Serial direct connect not supported.
13.	Fix	Serial over LAN and IPMI over LAN connections may terminate unexpectedly under certain conditions.
14.	Fixed	Intermittent beep code 1-5-2-1 when booting with dual processors.
15.	Fixed	Power Supply population errors may not appear in SEL.
16.	Fix	Fan 5 may report a reading of 0 RPM after BMC is updated.
17.	Fixed	BMC may not respond to the IPMI command, <i>Send Message</i> sent via LAN.
18.	Fix	Fans may take a long time to slow down after fan boosting.

No.	Plans	Description of Errata
19.	Fixed	System requires approximately 35 seconds after AC power applied before power button responds.
20.	Fixed	SEL events for HSC may appear after DC cycle.
21.	Fixed	Fans may run faster than expected after exiting BIOS setup.
22.	Fixed	System fault LED may report incorrect status for some events.
23.	No Fix	Fan removal does not generate SEL even.
24.	Fixed	Power supply redundancy state is misleading when only one power supply is installed.
25.	No Fix	PCI-X slots 1 and 2 do not meet the letter of the Server System Infrastructure (SSI) Entry-Level Electronics Bay (EEB) Specification revision 3.61.
26.	Fixed	Serial ATA (SATA) HDDs may be marked offline when populated behind a second Serial Attached SCSI (SAS) expander based drive enclosure.
27.	Fixed	Failures seen installing to a SATA drive when SATA is set to Legacy in the BIOS setup.
28.	Fixed	System Hangs after disabling onboard video in the BIOS setup.
29.	Fixed	The SMBIOS entry point may not be visible under certain hardware configurations.
30.	Fixed	Fans occasionally running too fast after the BIOS reset.
31.	Fixed	SAS SW RAID option is erroneously available in the BIOS setup after loading optimal default settings on the S5000PSLROMB server board.
32.	Fix	RAID Web Console 2 Utility displays "Unexpected Sensor" warning message in Microsoft Windows* operating system.
33.	Fixed	PS/2 keyboards and mice may stop functioning after Red Hat* Enterprise Linux is installed.
34.	Fix	HSC and LCP updates may take a long time.
35.	No Fix	SuSE* Linux Enterprise Server may not install successfully with Intel® Embedded Server RAID Technology II enabled.
36.	No Fix	Red Hat* Enterprise Linux 4 and the BIOS setup display a different L2 cache size for the Intel® Xeon® Processor 5300 Series.
37.	Fixed	Change Logo Utility causes BIOS corruption.
38.	Fixed	Microsoft Windows* System Event Viewer may record ID 11 error event.
39.	Fixed	POST screen may generate "NMI has been received – System Halted" message after the system reboots.
40.	Fixed	S5000PSLSAS software RAID 5 cannot be configured.
41.	No Fix	SuSE* Linux Enterprise Server unable to boot after basic installation.
42.	No Fix	Red Hat* Enterprise Linux may report the wrong processor speed.
43.	Fixed	A kernel panic is likely to be observed with Red Hat* Enterprise Linux 4 or SuSE* Linux Enterprise Server 9 when SpeedStep is disabled in the BIOS menu.
44.	Fixed	SAS software RAID 5 activation key may NOT be detected.
45.	Fixed	Microsoft Windows* operating systems without the service pack will exhibit blue screen with BIOS BIO79 and 81.
46.	Fixed	Fails PXE boot from on-board NIC 2 and neither on-board NIC works under DOS with BIOS R0079 and R0081.
47.	Fixed	SAS Embedded Server RAID Technology II RAID 5 consistence check fails in ESRTII BIOS console only if hard drives docked in expander HSBP.
48.	Fixed	Sluggish system performance may be experienced with BMC60.
49.	Fixed	Microsoft Windows Server 2003* R2 SP2 may exhibit blue screen during an operating system boot or shutdown with a specific version of I/OAT driver.
50.	Fixed	Recent Intel® Server RAID Adapters fail to activate RAID BIOS Console by Ctrl+G in S5000PSL and/or S5000XVN PCI slot 4.

No.	Plans	Description of Errata
51.	Fixed	Microsoft Windows Server 2008* and/or Microsoft Windows Vista* may report Performance Power Management error.
52.	Doc	'Fdisk' command under Red Hat* Enterprise Linux Server 5 Update 1 may report Intel® Embedded Server RAID Technology II RAID 1 array as two hard disk drives.
53.	Fixed	Platform Confidence Test (PCT) may fail with BIOS89 and later version loaded.
54.	Fixed	BIOS 94 does not support mixed stepping E-0 and C-0 processors
55.	No Fix	S5000PSL/S5000XSL cannot boot from SATA CD/DVD ROM using a "bootable" Microsoft* DOS CD/DVD when RAID (or AHCI) is Enabled in the BIOS setup.
56.	Fixed	System may not boot after multiple DC power cycles with BIOS revision R0098.
57.	No Fix	System will not skip CD/DVD drive with BIOS revision R0098 when RMM2 installed

Table 2. Documentation Changes

No.	Plans	Description of Documentation Change
1.		None

The following are in-depth descriptions of each erratum / documentation change indicated in Table 1. The following errata and documentation change numbers correspond to the numbers in the tables.

## Errata

---

### 1. Console Redirection baud rate setting auto changing to 19.2K with Serial Over LAN (SOL) active

Problem	If configuring an SOL connection, the only baud rate allowed is 19.2K. If any other baud rate is selected, the system will always revert back to 19.2K after the DC cycle.
Implication	Users who require a different baud rate for their application cannot configure this.
Status	This erratum was fixed in BIOS revision R0045.
Workaround	None.

### 2. Serial Over LAN (SOL) unable to redirect DOS output

Problem	No SOL output is seen when booted to DOS. SOL will only redirect F2 Setup and POST output.
Implication	Users who require SOL to redirect DOS output cannot use this feature.
Status	This erratum was fixed in BIOS revision R0054.
Workaround	None.

### 3. Password on boot not supported

Problem	If an "admin" or "user" password is set in the BIOS setup, this is required before the user can access the BIOS Setup. There is no option to configure a password during POST before the server will boot.
Implication	Users cannot create and require a password on boot.
Status	Intel does not intend to fix this erratum.
Workaround	None



#### 4. SAS Software RAID option is not enabled in the initial BIOS release.

Problem	The SAS Software RAID feature that was available in pre-production BIOS releases is not available in the initial production BIOS release. The option ROM that allows configuration of SAS Software RAID still has several defects logged against its functionality and was deemed not ready for production by Intel at this time.
Implication	Users who require or were planning to use this feature in their production environments must wait for a post-launch BIOS release which will have this feature enabled.
Status	This erratum was fixed in BIOS revision R0057.
Workaround	Several hardware RAID options are readily available and supported by Intel server boards. Consult the product Tested Hardware and Operating System list for a variety of Hardware Options. No workarounds for SAS Software RAID are available.

#### 5. Secondary HSC backplane FW not visible in the BIOS setup

Problem	If two backplanes are installed in the server system, the HSC revision on the secondary backplane is not currently being displayed in the BIOS Setup. This affects the Intel® Server Boards S5000PSL, S5000XSL, and S5000VSA in the Intel® Server Chassis SC5400.
Implication	Users may not be able to easily identify the HSC revision programmed in the backplane attached to the secondary backplane header.
Status	This erratum was fixed in BIOS revision R0045.
Workaround	Users must use the DOS utility, 'fwpiaupd', to probe and get the backplane HSC information. Boot to DOS and using the fwpiaupd.exe utility, which is used to flash the BMC and HSC code onto the server system, enter the following command: " <i>fwpiaupd -i -address={c0, c2}</i> " where c0= primary backplane address and c2= secondary backplane address. This provides you with the operational code revision for the HSC on each backplane.

#### 6. Removed as Duplicate

## 7. HSC and BMC versions intermittently not seen in the BIOS setup

Problem	BMC and HSC revision information is intermittently missing from the BIOS Setup.
Implication	HSC and BMC information is not easily found.
Status	This erratum was fixed in BIOS revision R0057.
Workaround	Users must use the DOS utility, 'fwpiaupd.exe', to probe and get the backplane HSC information. Boot to DOS and using the fwpiaupd.exe utility, which is used to flash the BMC and HSC code onto the server system, enter the following command: " <i>fwpiaupd -i -address={c0, c2}</i> " where c0= primary backplane address and c2= secondary backplane address. This provides you with the operational code revision for the HSC on each backplane.

To retrieve the BMC version information, use the same 'fwpiaupdt.exe' utility with the following command: "*fwpiaupdt -i -address=20*"

## 8. POST LEDs do not turn off after Operating System loads

Problem	The POST Code LEDs at the rear of the system do not turn off once POST completes and the operating system loads. The POST code LEDs will show [Green Red Green Red] at the rear of the system.
Implication	User may believe an error occurred since there are LEDs lit on the baseboard.
Status	This erratum was fixed in BIOS revision R0057.
Workaround	None.

## 9. Checkup7.exe (microcode update utility) is not storing microcode in the BIOS

Problem	The Checkup7.exe utility, which is used to update the processor microcode in a BIOS, is not working properly. The utility says it completes the flash update successfully; however, upon the next reboot, the microcode is not actually present in the BIOS.
Implication	Users cannot update their BIOS with a new processor microcode.
Status	This erratum was fixed in BIOS revision R0057.
Workaround	Users must update to the latest BIOS revision which includes the latest processor microcode releases. They cannot use this utility to add a microcode patch to the existing BIOS.

## 10. Intel® Server RAID Card SRCAS144E causes systems to reset multiple times before completing POST

Problem	With the Intel SRCAS144E adapter installed into the system, the system may become caught in a reset loop during POST. The system resets itself 4 to 5 times before completing POST. This is seen early in POST within the first seconds of power on and before video initialization. POST code LEDs show 0x21 "Chipset" Initializing a chipset component.
Implication	POST takes approximately 15-20 seconds longer to complete.
Status	This erratum was fixed in BIOS revision R0057.
Workaround	Moving the card into a different slot sometimes resolves this issue. Populating the card in a slower bus (x4 or x8) seems to make this issue appear less frequently.

## 11. Change Logo utility does not save modified BIOS capsule files with correct extension

Problem	When using the Change Logo utility to modify a BIOS capsule file and replace the Intel Splash Screen logo with a new one, it fails to save the new capsule file with a .cap extension. The file produced has a .fd extension. The file is a capsule file, but it has the wrong extension.
Implication	Users may be confused and believe the utility is not saving the file in the correct format.
Status	This erratum was fixed in revision 4.16 of the utility
Workaround	When saving the file, on the Save As dialog box, select Capsule File (*.cap) in the Save as Type drop-down box. Then in the File Name box, type the name of the file with the .cap extension. It is important you include the ".cap" extension in the file name or else the Change Logo utility saves the file with the incorrect extension.  If you forget to include the ".cap" in the file name, but you selected "Capsule File (*.cap)" in the Save as Type drop-down box, you can rename the file from a .fd extension to a .cap extension and this will also work.

## 12. IPMI over Serial direct connect not supported

Problem	Intel® S5000 family Server Boards list support for IPMI access via serial direct connect. Serial access to the BMC is not supported at this time.
---------	---

Implication	Users should use the IPMI over LAN interface to connect to the BMC. This only affects serial and terminal mode access to the BMC. This does not affect BIOS console redirection via serial and operating system redirection via serial.
Status	This erratum may be fixed in a future firmware revision and hardware revision.
Workaround	None.

### **13. Serial over LAN and IPMI over LAN connections may terminate unexpectedly under certain conditions**

Problem	During an active Serial over LAN connection or during an active IPMI over LAN connection to the BMC, the connection may be lost intermittently during a DC cycle or reset.
Implication	The user's connection may be lost causing the user to reconnect the session.
Status	This erratum may be fixed in a future firmware revision.
Workaround	None.

### **14. Intermittent beep code 1-5-2-1 when booting with dual processors**

Problem	During POST, the system may pause at POST code 0x13 (SMM Initialization). If dual processors are installed, this may result in a 1-5-2-1 beep code and a processor event in the System Event Log (SEL).
Implication	The system may log erroneous errors in the SEL or via beep code. Under some conditions, the system may halt at 0x13 and require an AC cycle.
Status	This erratum is fixed in BMC release 47 and later releases.
Workaround	If an error is encountered, AC cycle the system and the system should run normally.

### **15. Power Supply population errors may not appear in SEL**

Problem	The BMC will not give any indication if a single power supply is improperly installed in a redundant chassis.
Implication	Some chassis require power supplies to be installed in specific slots if a single power supply is installed.
Status	This erratum was fixed with BMC 36 and FRUSDR 20.

Workaround None.

## 16. Fan 5 may report a reading of 0 RPM after BMC is updated

**Problem** After a BMC update, Fan 5 may not return an accurate reading until AC power is cycled.

**Implication** Intel® Server Management Software and other software may display a reading of 0 RPM for this sensor. The BMC may respond as though this fan had failed and fan redundancy was lost. This would cause the system fault LED and fan status LED to indicate a failure for this sensor, and the fans will run in a high speed boost state.

**Status** This erratum may be fixed in a future firmware revision.

**Workaround** AC cycle the system again and the system should run normally.

## 17. BMC may not respond to the IPMI command, *Send Message* sent via LAN

**Problem** The BMC may not respond correctly to a *Send Message* command from the LAN channel to the IPMB channel. This issue only affects an IPMI 2.0 based RMCP+ session—not an IPMI 1.5 based RMCP session.

**Implication** Remote IPMI over LAN software cannot forward commands to the IPMB bus.

**Status** This erratum was fixed in BMC firmware revision 50.

**Workaround** Software developers should use IPMI 1.5 based sessions to bridge commands to the IPMB channel.

## 18. Fans may take a long time to slow down after fan boosting

**Problem** System fans that boost (due to an increased processor temperature) may not return to normal speed immediately after the processor temperature returns to normal.

**Implication** If the system fans boost due to a high processor temperature, the BMC will not restore the fans to a normal speed for a similar amount of time as they spent in a boosted state. For example, if a high processor temperature caused the fans to boost for 5 minutes, the fans would not return to normal for 5 minutes after the processor temperature returned to normal.

**Status** This erratum may be fixed in a future firmware revision

**Workaround** The fans will return to normal on their own over time.

## 19. System requires approximately 35 seconds after AC power applied before power button responds

Problem	The BMC requires over 35 seconds to fully initialize the system after an AC cycle before the system can be powered on.
Implication	After an AC cycle, a user must wait ~35 seconds before the power button responds. The BMC causes the front panel LEDs to blink in an alternating amber/green pattern while the BMC initialization is in progress. Users should wait until the LED stops blinking in this pattern before pressing the power button.
Status	This erratum was fixed in BMC firmware revision 50.
Workaround	None.

## 20. SEL events for HSC may appear after DC cycle

Problem	The HSC may log critical and non-critical temperature events in the SEL after DC cycle.
Implication	The SEL events are deassertion events, which are not an indication of a problem with the system. Users can ignore these events as they are not errors or an indication of a problem in the system.
Status	This erratum was fixed by HSC v.2.02 and later version.
Workaround	None.

## 21. Fans may run faster than expected after exiting BIOS setup

Problem	Some system fans may run faster after exiting the BIOS setup using the Save and Exit option.
Implication	The system may generate more fan noise than normal.
Status	This erratum was fixed in BMC firmware revision 49.
Workaround	The system must be AC cycled or allowed to boot to the operating system and then reset to restore fans to their normal speeds.

## 22. System fault LED may report incorrect status for some events

Problem	The system fault LED may report incorrect status for some events. The proper LED state is described in the server board TPS, but some events may not reflect the states described in the TPS.
---------	---

Implication	The user may receive incorrect indication via the system fault LED. The user should verify the system state by looking at the SEL. No event is reported as a less severe status than expected, but may display with a higher severity status.
Status	This erratum was fixed with BIOS R0065, BMC 55 and FRUSDR 40.
Workaround	None

### **23. Fan removal does not generate SEL event**

Problem	Fan removal does not trigger a fan failure event.
Implication	Fan removal generates a “fan presence deassertion” event instead of a fan failure event. When the fan is reinstalled, a “fan presence assertion” event is generated.
Status	No fix.
Workaround	None.

### **24. Power supply redundancy state is misleading when only one power supply is installed**

Problem	If a single power supply is installed in a chassis that supports redundant power supplies, the BMC indicates the power supply redundancy state as redundant.
Implication	In a single power supply configuration, ignore the redundancy sensor. Redundant chassis with fully redundant power supplies will accurately reflect the redundancy status.
Status	This erratum was fixed by BMC 36 and FRUSDR 20.
Workaround	None.

### **25. PCI-X slots 1 and 2 do not meet the letter of the Server System Infrastructure (SSI) Entry-level Electronics Bay (EEB) Specification revision 3.61**

Problem	PCI-X slots 1 and 2 were placed physically on the board 0.25 mm away from the specified dimension called out in the SSI EEB Specification revision 3.61 due to trace routing considerations.
Implication	The SSI EEB Specification revision 3.61, Figure 2 denotes the reference pin 1 location at 31.12 mm aft of the reference datum. Current location of the PCI-X slots 1 and 2 are 31.37 mm aft of the reference datum. Due to the many

variables in board and chassis design, this small deviation is expected to have little or no customer impact.

Status This erratum will not be fixed.

Workaround None.

## **26. Serial ATA (SATA) HDDs may be marked offline when populated behind a second Serial Attached SCSI (SAS) expander based drive enclosure**

Problem When using dual-expander SAS based drive enclosures, SATA drives may become marked offline in the second expander drive enclosure.

Implication Users who implement more than one fully populated SAS expander drive enclosure while using SATA disk drives may experience intermittent drive failures during operation.

Status This issue was fixed in HSC firmware revision 2.02.

Workaround None.

## **27. Failures seen installing to a SATA drive when SATA is set to Legacy in BIOS setup**

Problem If a user has SATA set to "Legacy" in the BIOS Setup and tries to install an operating system, the installation may fail.

Implication Users who require SATA to be configured in Legacy mode may not be able to get their operating systems to install properly.

Status This erratum was fixed in BIOS revision R0057.

Workaround Leave SATA in Enhanced mode if possible. No workaround for the Legacy mode issue.

## **28. System Hangs after disabling Onboard Video in BIOS setup**

Problem After disabling Onboard Video in BIOS setup, the system hangs during POST.

Implication Users cannot disable onboard video via BIOS Setup

Status This erratum was fixed in BIOS revision R0057.



**Workaround** Adding in a video controller automatically disables the onboard video. It is not necessary to manually disable the video controller via BIOS setup. There is no workaround for configurations that do not include video controller support.

## 29. The SMBIOS entry point may not be visible under certain hardware configurations

**Problem** The server BIOS maintains an area in memory to act as an entry point to locate the SMBIOS area. This entry point includes the anchor string “\_SM\_”, memory pointers and information about the SMBIOS area as required by the SMBIOS specification. This information is dynamically created by the BIOS during POST and is placed in a required memory range between 000F0000h-000FFFFFh. Hardware configurations that require large amounts of memory at POST (option ROM space or I/O configuration space) could fill up this memory range and the SMBIOS entry point cannot be created correctly.

**Implication** This problem manifests as an inability for software to locate the SMBIOS records. This can affect management software and also some Intel-provided update utilities including BIOS update utilities and FRUSDR update utilities. An error may also display in the BIOS error manager. Intel update utilities will generate an error and abort before performing an update.

**Status** This erratum is fixed in BIOS release R0060 and later release.

**Workaround** If a specific hardware configuration experiences this issue, remove add-in PCI and PCIe cards to reduce the amount of add-in card resource space used. Perform the system update (BIOS, FRUSDR) and replace the add-in cards.

## 30. Fans occasionally running too fast after BIOS reset

**Problem** From the BIOS setup screen, when you hit F10 to save and reset, the PWM will often come up at 30 hz instead of 23 kHz. Fan are running too fast in this mode. Hitting the Reset button causes the fan speed to return to normal.

**Implication** If users do not perform a hard reset from the front panel, the fans in the system may run too fast and cause unnecessary noise.

**Status** This erratum is fixed in BMC Revision 49 and later releases.

**Workaround** In order to work around this issue, you must execute a hard reset from the front panel. This resets the PWM circuitry back to the correct frequency.

### 31. SAS SW RAID option is erroneously available in BIOS setup after loading optimal default settings on the S5000PSLROMB server board

Problem	Onboard SAS software RAID is not a function available on the S5000PSLROMB server board. In the BIOS setup, <i>AdvancedMass Storage Controller Configuration</i> , the option to configure SAS as SW RAID is available after pressing <F9> to load optimized defaults. This option is not available unless <F9> is pressed.
Implication	If SAS software RAID is “enabled” after pressing <F9>, the SAS RAID controller SROMBSAS18E included in this system is not available to the user.
Status	This erratum is fixed in BIOS Revision R0077 and later revision.
Workaround	After pressing <F9> to load optimum defaults, do not enable SAS SW RAID in the BIOS setup. After saving the setting and exiting, the option to enable/disable SAS software RAID is not available to the user.

### 32. RAID Web Console 2 Utility Displays “Unexpected Sensor” Warning Message in Microsoft Windows\* Operating System

Problem	The warning message of “unexpected sensor” might display in the RAID Web Console 2 Utility when there seems to be no functional issues for system.
Implication	This warning message is only seen in the Microsoft Windows* operating system. Old version RAID firmwares (before v.89) used not to support any communication to the SEP (Storage Enclosure Processor) on backplanes. When the firmware was modified to increase its capabilities and support of all the SEP devices out in the world, the Intel® Server Board S5000PAL related chassis backplane is one of the few that do not respond as expected to the inquiry command, so the error is rolled up and captured in the log. This is a harmless message against the backplane SEP device and does not cause any problems with the array or the drives.
Status	This erratum may be fixed in a future firmware revision.
Workaround	None.

### 33. PS/2 keyboards and mice may stop functioning after Red Hat\* Enterprise Linux is installed

Problem	After installing Red Hat* Enterprise Linux on a system with BIOS release R0045, the PS/2 keyboard and mouse stop working; however, USB keyboards and mice work fine.
Implication	If a PS/2 keyboard and mouse are installed, users cannot use the Linux operating system.
Status	This erratum is fixed in BIOS release R0054 and later release.
Workaround	If the user goes into the BIOS setup and disables port 60/64 emulation, PS/2 keyboards and mice will continue to work. If USB keyboards and mice are used, the user should enable port 60/64 emulation.

### 34. HSC and LCP updates may take a long time

Problem	The Hot Swap Controller (HSC) and Intel® Local Control Panel (LCP) updates may take a long time. The time to complete each update may exceed 30 minutes.
Implication	Updating HSC and LCP may take a long time.
Status	This erratum may be fixed in a future firmware revision.
Workaround	None.

### 35. SuSE\* Linux Enterprise Server may not install successfully with Intel® Embedded Server RAID Technology II enabled

Problem	If SuSE* Linux Enterprise Server is being installed with Intel® Embedded Server RAID Technology II enabled, the RAID array may not be detected after the driver is loaded, which results in an installation failure.
Implication	The AHCI module inside the operating system is loaded prior to the third party driver, and therefore may take control of the RAID controller. This results in an installation failure.
Status	Users cannot load a third party RAID driver and the AHCI driver simultaneously in SuSE* Linux Enterprise Server; doing so may cause installation failures.
Workaround	The "brokenmodule-ahci" command can prevent AHCI from loading during installation. At the very first install screen, press F6 to load a driver. In the text

tab, type `brokenmodules=ahci`; this allows the installation to complete successfully.

### 36. Red Hat\* Enterprise Linux 4 and BIOS setup display a different L2 cache size for the Intel® Xeon® Processor 5300 Series

Problem	In Red Hat* Enterprise Linux 4, the Intel® Xeon® Processor 5300 Series L2 cache size is displayed as 4 MB; while in the BIOS setup, the cache size is displayed as 8 MB.
Implication	In the BIOS setup, the system reports the total L2 cache size as 8 MB due to the 4MB + 4MB structure of the processor. The Intel® Xeon® processor 5300 Series is similar to a package of two sets, each with a 4 MB L2 cache size. In each set, the two cores share the 4 MB cache. Red Hat* Enterprise Linux 4 views the processor per logical CPU thread. Each logical thread (each set) has access to only 4 MB cache, and Red Hat* Enterprise Linux 4 reports it as such.
Status	The different L2 cache size display is due to the different cache size reporting mechanisms of Red Hat* Enterprise Linux 4 and BIOS setup, and is not an incorrect display by the operating system.
Workaround	None.

### 37. Change Logo Utility causes BIOS corruption

Problem	Any board flashed with a version of BIOS release R0064 edited with the Change Logo Utility no longer boots. The board hangs with “Off-Off-Red-Green” shown on the Post Code LEDs at the rear of the board.
Implication	You cannot use the Change Logo Utility with BIOS release R0064.
Status	This erratum is fixed in BIOS release R0066 and later releases.
Workaround	None.

### 38. Microsoft Windows\* System Event Viewer may record ID 11 Error Event

Problem	In the Microsoft Windows* operating system, the Event Viewer’s System Log may record an error event; the source is LSI_SAS and the event ID is 11.
Implication	The problem may occur because the controller is sending an unsupported command to the enclosure management device. This error does not affect functionality; therefore, you can ignore the error.
Status	This erratum was fixed in Intel® Embedded Server RAID Technology II firmware

revision: SAS firmware revision -- v.01.16.00.00; MPT OpROM revision -- v.6.10.00; SAS ESRT2 OpROM v. A.01.10241435I.

Workaround None.

### 39. POST screen may generate “NMI has been received – System Halted” message after the system reboots

**Problem** POST screen may generate "NMI has been received - System Halted" message after the system reboots.

**Implication** Along with this error, sometimes “Bus Uncorrectable Error” might also be recorded to System Event Log (SEL).

**Status** This erratum is fixed in BIOS release R0066 and later releases.

**Workaround** Reboot the system again.

### 40. S5000PSLSAS software RAID 5 cannot be configured

**Problem** When users install the SAS software RAID 5 key on the board, there is no SAS software RAID 5 option that displays in the SAS RAID configuration menu.

**Implication** This problem may occur because of old versions of SAS RAID firmware on the server board.

**Status** This erratum was fixed in Intel® Embedded Server RAID Technology II firmware revision: SAS firmware revision -- v.01.16.00.00; MPT OpROM revision -- v.6.10.00; SAS ESRT2 OpROM v. A.01.10241435I.

**Workaround** None.

### 41. SuSE\* Linux Enterprise Server unable to boot after basic installation

**Problem** During a SuSE\* Linux Enterprise Server installation, if a USB floppy drive is used to load the mass storage driver, SuSE\* Linux Enterprise Server may not boot after basic installation. The following message may display:

```
resume device /dev/sdb1 not found (ignoring)

waiting for device /dev/sdb2 to
appear.....not found -- exiting
to /bin/sh

$
```

Implication	During installation, the USB floppy device is recognized as sda, and the mass storage is recognized as sdb. After reboot, the mass storage is now recognized as sda, but SuSE* Linux Enterprise Server still tries to load system files from sdb. To resolve this problem, you must modify the grub menu list file and the fstab file.
Status	No Fix.
Workaround	<a href="http://support.intel.com/support/motherboards/server/sb/CS-025446.htm">http://support.intel.com/support/motherboards/server/sb/CS-025446.htm</a> describes this problem and its workaround.

#### **42. Red Hat\* Enterprise Linux may report the wrong processor speed**

Problem	In Red Hat* Enterprise Linux, the operating system may report the wrong processor speed. Example: Processor speed is 3.0 GHz; the operating system shows it as 3300 MHz.
Implication	This symptom is operating system-related. Although it does not reflect the processor speed correctly, the processor's actual running speed corresponds with its design capacity. It is harmless to the system and can be ignored.
Status	Ignore the processor speed in Red Hat* Enterprise Linux.
Workaround	None.

#### **43. A kernel panic is likely to be observed with Red Hat\* Enterprise Linux 4 or SuSE\* Linux Enterprise Server 9 when SpeedStep is disabled in BIOS menu**

Problem	When SpeedStep is disabled in the BIOS menu, a kernel panic along with a Blue Screen is likely to be observed with Red Hat* Enterprise Linux 4 or SuSE* Linux Enterprise Server 9.
Implication	This makes the operating system installation or system boot halt with a kernel panic warning message.
Status	This erratum is fixed in BIOS Release R0079 and later releases.
Workaround	None.

#### **44. SAS software RAID 5 activation key may NOT be detected**

Problem	SAS software RAID 5 activation key may NOT be detected in the Intel® S5000PSLSAS server board. On the system POST screen, there is no
---------	---

message to report that SAS software RAID 5 activation key is presented and software RAID 5 function is not available to configure.

Implication	This is SAS software RAID firmware related.
Status	This erratum was fixed in Intel® Embedded Server RAID Technology II firmware later than the following revisions: SAS firmware revision -- v.01.22.00.00; MPT OpROM revision -- v.6.16.00; SAS ESRT2 OpROM v.A.01.07101204I.
Workaround	None.

#### **45. Microsoft Windows\* operating systems without service pack will exhibit blue screen with BIOS 79 and 81**

**Problem** If a user attempts to install Microsoft Windows\* without an integrated service pack, it will “blue screen” during the installation process if BIOS R0079 or BIOS R0081 is on the Intel Server Board. Conversely, if a user upgrades the system BIOS to BIOS R0079 or R0081 *prior* to installing the appropriate service pack, the system will blue screen. Starting in BIOS R0079, support for enhanced sleep states was added. This addition to the BIOS requires the integration of the Microsoft Service Pack into the operating system installation process to understand the extended sleep state support.

The following is a list of Microsoft\* operating systems and required service packs:

- Microsoft Windows Server 2003\* 32-bit and 64-bit requires Service Pack 1
- Microsoft Windows SBS 2003\* requires Service Pack 1

**Implication** Users cannot install Microsoft Windows\* or upgrade the system BIOS to BIOS R0079 or R0081 without the required service pack integrated into the operating system installation process or install the required service pack before the BIOS update.

**Status** This erratum was fixed in BIOS R0084. Users need to upgrade BIOS to R0084 or a later version, then disable Deep C-state Support in BIOS setup (Advanced BIOS menu -> Processor submenu) before installing or booting a Microsoft Windows\* operating system without the required service pack.

**Workaround** Users need to remain on BIOS R0076, use a Microsoft Windows\* installation process that includes the service pack integrated into the installation, or install Microsoft Windows\* and service pack prior to updating to BIOS R0079 or R0081. Additionally, the Release 2 versions of Microsoft Windows Server 2003\* do not exhibit this issue. Use of this version of Microsoft Windows\*, if possible, is also another valid workaround.

#### **46. Fails PXE boot from on-board NIC 2 and neither on-board NIC works under DOS with BIOS R0079 and R0081**

Problem	With BIOS R0079 or R0081 installed on the Intel® Server Boards S5000PSL/S5000XSL, it fails PXE boot from on-board NIC 2 and neither on-board NIC works under DOS.
Implication	The server fails to connect the PXE server through the on-board NIC 2 and on-board NICs do not work under DOS.
Status	This erratum was fixed with BIOS R0084.
Workaround	None.

#### **47. Intel® Embedded Server RAID Technology II SAS RAID 5 consistence check fails in BIOS console only if hard drives are docked in expander HSBP**

Problem	If the Intel® Embedded Server RAID Technology II SAS RAID 5 volume includes hard drives docked in expander HSBP, the RAID 5 volume consistence check fails in the Intel® Embedded Server RAID Technology II BIOS console.
Implication	Consistence check works with other RAID volume types like RAID 0, 1, 10. Consistence check only fails if the Intel® Embedded Server RAID Technology II SAS RAID 5 volume includes hard drives docked in the expander HSBP, and only fails in the Intel® Embedded Server RAID Technology II BIOS console.
Status	This erratum was fixed with Intel® Embedded Server RAID Technology II BIOS Version A.01.09121449I, which is included in Intel® Embedded Server RAID Technology II firmware package: ESRT2_LSI1064e_1068_MPT_MegaSR_FW_OpROM_v_2007_12_05.
Workaround	Users may run Intel® Embedded Server RAID Technology II RAID 5 consistency check under the operating system using the Intel® RAID Web Console 2.

#### **48. Sluggish system performance may be experienced with BMC60**

Problem	An issue with BMC 60 is causing incorrect interpretation of the user-selected BIOS Setup Open Loop Thermal Throttling (OLTT) options. Advanced BIOS Setup contains OLTT selections for Performance Mode and Acoustic Mode. BMC 60 is recognizing a Performance Mode selection in the BIOS setup as an Acoustic mode request. Acoustic Mode selection in the BIOS setup is being disregarded and fail safe defaults for Fan Profiles are enforced. This misinterpretation can manifest the BIOS/BMC interaction causing a throttling condition slowing down the system performance significantly.
---------	--



Implication	Systems set to Performance Mode are incorrectly being configured in Acoustics Mode which could make the system more susceptible to overheating, especially in 1U chassis, or performance degradation may be seen due to memory throttling rather than fan boosts being used to cool the memory. Systems being configured to Acoustics Mode in the BIOS are actually being set up in fail safe state.
Status	This erratum was fixed in BMC 62.
Workaround	None.

#### **49. Microsoft Windows Server 2003\* R2 SP2 may exhibit a blue screen during an operating system boot or shutdown with a specific version of I/OAT driver**


Problem	Microsoft Windows Server 2003* R2 SP2 may exhibit a blue screen during an operating system boot or shutdown. The issue happens only with Ver.1.2.78.6 of the I/OAT driver and only if I/OAT is enabled in the BIOS Setup. This symptom was seen with the I/OAT driver in Intel NIC driver package Version 12.3.
Implication	In the recent I/OAT driver, Microsoft* has changed a structure in their NetDMA API. It is not backward compatible with the previous version of the API.
Status	This erratum is fixed in IOAT driver ver 1.2.79.6 in Intel NIC driver package Version 13.1.1.
Workaround	None.

#### **50. Recent Intel® Server RAID Adapters fail to activate RAID BIOS Console by Ctrl+G in S5000PSL and/or S5000XVN PCI slot 4**

Problem	Intel® RAID Controllers SRCSASJV, SRCSASRB, SRCSATAWB, SRCSASBB8I and SRCSASLS4I may fail to activate RAID BIOS Console by Ctrl+G after installed into PCI Slot 4 on the Intel® Server Board S5000PSL or Intel® Workstation Board S5000XVN Implication Fail to configure RAID in PCI slot 4.
Status	This erratum was fixed with BIOS R0094
Workaround	Install RAID cards into a different PCI Express* slot other than slot 4.

## 51. Microsoft Windows\* Server 2008 and/or Microsoft Windows Vista\* may report Performance Power Management error

**Problem** Microsoft Windows\* Server 2008 and/or Microsoft Windows\* Vista in Intel® Server Board S5000PSL and/or Intel® Workstation Board may have a Performance Power Management error in the Microsoft Windows\* System Event Log like the following illustration:



**Implication** Current version of the BIOS displays a default dummy PSS object (P-State info) in ACPI space for processors that do not support Enhanced Intel® SpeedStep® Technology to indicate no P-State supported; however, this is interpreted as a Performance Power Management error in the Operating System log. This is a harmless message and does not impact system performance or functionality.

**Status** This erratum is fixed by BIOS91.6

**Workaround** None.

## 52. 'Fdisk' command under Red Hat\* Enterprise Linux Server 5 Update 1 may report an Intel® Embedded Server RAID Technology II RAID 1 array as two hard disk drives

Problem	Sometimes, 'fdisk' command under Red Hat* Enterprise Linux Server 5 Update 1 may report an Intel® Embedded Server RAID Technology II (ESRTII) RAID 1 array as two hard disk drives. In the correct way, the Intel® ESRTII RAID 1 array should be detected as one hard disk drive.
Implication	Following the driver installation guide on the Intel® ESRTII Linux driver README file will have the RAID 1 array being detected by 'fdisk' correctly.
Status	A more detailed driver installation guide is provided with Intel® ESRTII Linux driver v.10.21.0507.2008.
Workaround	None.

## 53. Platform Confidence Test (PCT) may fail with BIOS 89 and later version loaded

Problem	Customer may experience problems when they run PCT on Intel® Server Board S5000PSL with BIOS 89 and later version loaded. There are two types of test options when a customer runs PCT test, Quick Test, and Comprehensive Test. The customer may see the following behavior during the PCT test.
---------	---

Quick Test	***ERROR T.EXE Unknown error:MSDRAM64.EXE Standard Error Code = 01300005
Comprehensive Test	System hangs at Probing ICH

Status	This erratum was fixed with BIOS R0094.
Workaround	This issue is caused by the incompatibility between the BIOS and PCT; it will not impact system stability or performance. Customer can ignore this issue or roll back to BIOS 85 to run the PCT.

## 54. BIOS 94 does not support mixed stepping E-0 and C-0 processors

Problem	BIOS code specifically designed to allow support for mixed stepping processors was not included in BIOS R0094.
Implication	The use of mixed stepping E-0 and C-0 processors and BIOS R0094 may cause erratic system behavior such as operating systems failing to load or install.

Status This erratum was fixed in BIOS R0096 and later version.

Workaround None.

### **55. S5000PSL/S5000XSL cannot boot from SATA CD/DVD ROM using a “bootable” Microsoft\* DOS CD/DVD when RAID (or AHCI) is Enabled in the BIOS setup**

Problem Users cannot boot S5000PSL/S5000XSL from SATA CD/DVD ROM using a “bootable” MSDOS based CD/DVD when RAID (or AHCI) is enabled in the BIOS Setup.

Implication Users needing to boot to any MS-DOS based diagnostic, pre-install, or application CDs (for example, Bart’s PE), are limited to using only the “IDE” mode setting in BIOS. Please note: Operating system installation CDs are not affected by this issue since they typically use “iso-linux”.

Status This is a known limitation. Whenever the RAID (or AHCI) setting is selected, the Advanced Host Controller Interface Option ROM is loaded. Unfortunately, AHCI is not supported by the Microsoft\* Disk Operating System (MS-DOS).

Workaround None.

### **56. System may not boot after multiple DC power cycles with BIOS revision R0098**

Problem If console redirection and legacy OS redirection are both enabled in BIOS setup, the system may hang early in POST after multiple DC power cycles.

Implication Users may occasionally experience system hangs during POST after multiple power cycles if console redirection and legacy OS redirection have been configured as enabled in BIOS setup.

Status This issue may be fixed in a future BIOS revision.

Workaround A soft system reboot (<CTL> <ALT> <DEL>) will result in a subsequent successful completion of POST.

### **57. System will not skip CD/DVD drive with BIOS revision R0098 when RMM2 installed**

Problem	If RMM2 is installed and CD/DVD drive is the first BIOS boot option, the system will not skip CD/DVD drive as expected when there is no bootable media in the drive.
Implication	Users would experience system boot failure when RMM2 is installed and no bootable media in CD/DVD drive
Status	This issue will be fixed in a future BIOS revision.
Workaround	No