



*This Technical Advisory describes an issue which may or may not affect the customer's product*

# Intel Technical Advisory

TA-0937-1

5200 NE Elam Young Parkway  
Hillsboro, OR 97124

October 23, 2009

## SR1670HV/S5500HV BMC firmware Issue

*Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.*

*The <SR1670HV/S5500HV> may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.*

### Products Affected

System: **SR1670HV (MM:902681) SR1670HVNA (MM:903665)**

Board: **BB5500HV (MM: 903447)**

### Description

BMC event log may report error messages on power supply while the system operates under typical conditions. Most often the messages are consecutive ones between "PSU slow fan" and "PSU over temperature". When that happens, the front panel message LED will turn red.

### Root Cause

The root cause is identified and the messages are confirmed to be false alarms. The cause is that the BMC regularly reads the PSU sensor status, and sometimes does not filter out invalid PSU sensor values that are triggering such false error messages.

### Corrective Action / Resolution

BMC firmware is updated to correctly filter out the false error messages. We recommend that customers update the product with the latest BMC firmware version 1.17 to avoid such false error message and LED indications.

Please contact your Intel Sales Representative if you require more specific information about this issue.

Enterprise Platforms & Services Division  
Intel Corporation