

intel® Technical Advisory

TA-0686-1

2800 Center Drive N
DuPont, WA 98327

January 30, 2004

Redundant Configuration Limitations Using First Revision of the Intel® Server Management Module SBCECMM

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice. The Intel® Server Compute Blade SBXL52 may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Products Affected

Intel® Server Management Module SBCECMM, TA C27061-001, PN C26927-001.
Intel® Blade Server Chassis SBCE, TA C23399-001

Description

Revision C26927-001 of the Intel® Server Management Module (MM) SBCECMM may not function properly when used as the secondary MM in a redundant configuration. In this configuration, both blowers may increase to 100%, multiple Blower Failures may be reported in the event log and all server blades may power down.

Root Cause

During production, support for a redundant MM feature was added to the product software. As a result, the need for a resistor change to the MM was identified to address a tolerance issue on the blower speed sensor. Due to this tolerance issue, some revision -001 MMs may work in a redundant configuration; however, many may experience the false blower failure described above.

Corrective Action / Resolution

A resistor change was made to the revision -002 MMs to correct this issue and provide support for the redundant MM feature.

All Intel Blade Server Chassis SBCE systems with a finished goods serial number of 882999A5107 or greater will contain a revision -002 MM; all Intel Blade Server Chassis SBCE systems with a serial number prior to 882999A5107 will contain a revision -001 MM. There was no MM# change to the SBCE when the revision -002 MM's were incorporated..

All orders for spare MMs will contain revision -002 MMs to ensure that any customer that orders a production-level spare MM for use as a secondary MM in a redundant configuration will receive a MM capable of supporting this feature/configuration.

Workarounds

The following are valid configurations that support redundant MM operation:

- Use a revision -001 MM as the primary MM and a revision -002 MM as the secondary/redundant MM
- Use two revision -002 MMs as both the primary and secondary MMs.

All Intel Blade Server Chassis SBCE systems are shipped with a single MM and will work in non-redundant mode using either a revision -001 or -002 MM.

To avoid false blower failures, customers must ensure that they are not using revision -001 MMs as both the primary AND secondary MM.

intel® Technical Advisory

TA-0686-1

2800 Center Drive N
DuPont, WA 98327

January 30, 2004

Please contact your Intel Sales Representative if you require more specific information about this issue.

Enterprise Platforms & Services Division
Intel Corporation