



This Technical Advisory describes an issue which may or may not affect the customer's product

Intel Technical Advisory

TA-932-1

5200 NE Elam Young Parkway
Hillsboro, OR 97124

June 8, 2009

Hot-swap controller may cause kernel panic under Linux or temporary system unresponsiveness under VMware ESX

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice. The products listed in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Products Affected

Intel® Server Systems:

SR2500ALLX
SR2500ALLXR
SR1550ALSAS
SR1550ALSASR

Intel® Server Chassis Accessories:

FALSASMP

Intel® RAID Controllers:

SRCSAS18E

Description

Under Linux, a kernel panic pointing to a failure in *megaraid_sas* driver may occur. Under VMware ESX, the system may become unresponsive for several minutes. In both cases the failure is followed by a "PD Reset" error showing up in the RAID Web Console 2 log with PD# corresponding to the hot-swap enclosure.

The issue exists only with LSI1068* based Hardware RAID controllers when used with Intel non-expander backplanes.

If a system has been stable for two months or longer, the issue is unlikely to occur on the system.

Root Cause

In case of a rare error condition on the I2C bus the hot-swap controller may not respond to some SES commands sent by the RAID controller. When this happens, it causes a time-out condition at the RAID controller level.

Corrective Action / Resolution

Intel has improved reliability of the I2C bus operation in the hot-swap controller firmware version 2.11 for all non-expander type backplanes.

The hot-swap controller firmware version 2.11 will be released around 8 June 2009.

It will be available for download at <http://support.intel.com/support/motherboards/server/>

Please contact your Intel Sales Representative if you require more specific information about this issue.

Enterprise Platforms & Services Division
Intel Corporation