



This Technical Advisory describes an issue which may or may not affect the customer's product

Intel Technical Advisory

TA-933-1

5200 NE Elam Young Parkway
Hillsboro, OR 97124

June 8, 2009

Expander enclosure may go offline causing a RAID failure

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice. The products listed in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Products Affected

Intel® Server Chassis Accessories:

AXX6DRV3GEXP

AXX4DRV3GEXP

Description

Under certain rare conditions the expander enclosure may go offline and the RAID controller will report a failure on all drives installed in the enclosure. With some RAID controllers, power-cycling the system will be needed to restore the enclosure operation after the failure.

The frequency of the failure under normal operating conditions is once in 1 to 12 months depending on the system configuration. The failure may occur with high probability during system FRUSDR update.

With AXX6DRV3GEXP and AXX4DRV3GEXP, the issue occurs only when the IPMB cable is connected between the enclosure and the server board.

Root Cause

When the hot-swap controller receives an IPMI command and a SES command at the same time, the processing of the commands may fail and may result in a firmware crash. This causes the expander enclosure to go offline

Corrective Action / Resolution

Intel has fixed the issue by preventing I2C transactions from preempting outgoing SSP transactions. The fix is included in firmware version 2.12 for the expander enclosures.

The hot-swap controller firmware version 2.12 for the expander enclosures will be released around 12 June 2009. It will be available for download at <http://support.intel.com/support/motherboards/server/>

Please contact your Intel Sales Representative if you require more specific information about this issue.

Enterprise Platforms & Services Division
Intel Corporation