

CAUTION

Risk of explosion if the battery is replaced with an incorrect type. Batteries should be recycled where possible. Disposal of used batteries must be in accordance with local environmental regulations.

ATTENTION!

If RAID is enabled in the BIOS, SATA ports 2 and 3 as labeled on the Desktop Board will become SATA ports 4 and 5 respectively in the Intel® Matrix Storage Console and the RAID Option ROM Utility (Ctrl-I). Exercise caution when replacing a failed drive within a RAID array. See the system documentation for more information.

D63606-003

*Other names and brands may be claimed as the property of others.
Copyright* 2007, Intel Corporation. All rights reserved.