



Intel Corporation  
5200 NE Elam Young Pkwy  
Hillsboro, OR 97124

August 10, 2007

Dear Intel Desktop Board Customer,

We regret to inform you that there is a misprint of network connectivity speed on the boxed Intel® Desktop Boards D945GCNL. The "Integrated 10/100/1000 Network Connection" is incorrectly labeled as "Integrated 10/100/100 Network Connection". However, the product (D945GCNL) is fully functional and there are no adverse effects in terms of usage and reliability.

Intel has taken steps to address this issue of misprint where box packaging, product documentation and websites have been updated with the correct network connectivity speed. All future Intel Desktop Boards D945GCNL built in the factories will now have this misprint rectified.

We sincerely apologize for any inconveniences or confusion caused by the misprinting and we appreciate your business.

Sincerely,  
Desktop Board Product Marketing  
Intel Corporation