

### **Server WHQL Testing Services**

### **Enterprise Platforms and Services Division**

# Intel® Server SE7320EP2

### **Server Test Submission (STS) Report**

For the Microsoft® Windows® Logo Program (WLP)

**Rev 1.0** 

#### June 27, 2005

This report describes the Intel® SE7320EP2 Server Platform Windows\* Logo Program test run conducted by Intel Enterprise Platforms and Services Division (EPSD).

#### Purpose of this WLP Submission:

System First Time submission for the Microsoft\* Designed for Windows Logo submission for the Intel® Server Board SE7320EP2.

Submission Type:	Reason for test run	Check one
First Time Submission	Initial Microsoft Designed for Windows logo submission. New product submission.	
System Update	Hardware update. (For example, update submission test run with new processor speeds.)	
BIOS Update	BIOS and/or Firmware update. (For example, update submission test run with new BIOS to support additional processor speeds.)	
OS Update	OS update. (For example, update submission test run to add Microsoft Designed for Windows Server 2003 logo to product.)	

### **Revision History and Disclaimers**

Revision History				
Revision	Revision Date Comments			
1.0	1.0 6/27/2005 Internal draft of the STS Report for Windows Server 2003 & Windows 2000 WLP Submission for Intel® Server Board SE7320EP2.			

THIS TEST REPORT IS PROVIDED "AS IS" WITH NO WARRANTIES WHATSOEVER, INCLUDING ANY WARRANTY OF MERCHANTABILITY, NONINFRINGEMENT FITNESS FOR ANY PARTICULAR PURPOSE, OR ANY WARRANTY OTHERWISE ARISING OUT OF ANY PROPOSAL, SPECIFICATION OR SAMPLE.

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document or by the sale of Intel products. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel retains the right to make changes to its test specifications at any time, without notice.

The hardware vendor remains solely responsible for the design, sale and functionality of its product, including any liability arising from product infringement or product warranty.

Intel, Pentium, Itanium and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

\* Other names and brands may be claimed as the property of others.

Copyright © 2004, Intel Corporation. All rights reserved.

# **Contents**

Revision History and Disclaimers	2
Introduction	4
Overview of Contents	
Terms and Definitions	
Server Board Submission Information	5
Intel Server Board Submission Report: Completion of WLP	5
Submission Information	
Submission ID	5
Submission Type	5
Product Category	5
Product Detail	5
General Product Information	5
Characterization (optional)	
Server Board Configuration Information	6
Processor	6
System Memory	
Power Management	
BIOS	
Bus Types	
Integrated Components	
Onboard Integrated Devices and Drivers	
Product Data for HCL: Completion of WLP	
Product Data	8
Hardware Compatibility Tests Used	9
Errata and Contingencies	10
Submission Readme File	
Testing Exceptions for Intel® Server SE7320EP2 Windows 2000 Submission	
Testing Exceptions for Intel® Server SE7320EP2 Windows Server 2003	
Tip Additional Information	
Annendix A - Submission History	13

### Introduction

This report provides an overview of the testing conducted on the Intel® Server Board SE7320EP2 without RAID enabled by Intel EPSD and provides details about this testing run.

#### **Overview of Contents**

Section	Content		
Introduction Brief descriptions of the sections in the report. Table listing terms and definitions.			
Server Product Submission Information	Submission information, ID # and final server board configuration upon completion of WLP including HW, Driver version, BIOS version, and Board AA number		
HCT	All HCT's used during testing		
Errata and Contingencies All Microsoft* errata or contingencies used during testing			

#### **Terms and Definitions**

Term	Definitions	
EPSD	Enterprise Platforms and Services Division	
HCL	Windows Hardware Compatibility List. You can view the HCL at: http://www.microsoft.com/whdc/hcl/search.mspx	
нст	Hardware Compatibility Tests. For latest Server HCTs visit: http://www.microsoft.com/whdc/hwtest/system/default.mspx	
STS	Server Test Submission Report published by EPSD	
WHDC	Windows* Hardware and Driver Central. Provides technical information, development and testing kits, newsletters and support information. <a href="http://www.microsoft.com/whdc/default.mspx">http://www.microsoft.com/whdc/default.mspx</a>	
WHOS	Windows Hardware Online Service – Secure online web site used to submit products for logo qualification and review submission history. <a href="https://winqual.microsoft.com/">https://winqual.microsoft.com/</a>	
WHQL	Windows* Hardware Qualification Lab. For more information visit the WHDC home page at: http://www.microsoft.com/whdc/default.mspx	
WLP	Windows Logo Program. For further information see:  http://www.microsoft.com/whdc/winlogo/default.mspx	
WTS	Workstation Test Submission Report published by EPSD	

### **Server Board Submission Information**

### Intel Server Board Submission Report: Completion of WLP

Data in this section reflects system submission information at the time of WLP Update submission.

### **Submission Information**

Submission ID			
Submission ID / Master ID	994359		
Submission Type			
	Check Submission Type	Comments	
First-Time Hardware and Driver Test Submission	$\overline{\checkmark}$		
System Update Test Submission			
Product Category			
Hardware Category	PC System or Server		
Operating System family	Windows Server 2003 and Window	ws 2000 (Supported Status only for 2000) families	
Product Detail			
General Product Information			
Equipment Type	Server		
Primary Target Market	Business/Corporate		
Compliance	All applicable requirements		
Characterization (optional)			
	Check appropriate options Comments		
Web Server	$\checkmark$		
SQL Database Server	<b>V</b>		
File Server			

### **Server Board Configuration Information**

Processor		
Quantity	2 (physical processors installed)	
Front Side Bus Speed	800 MHz	
Family/Model	Intel XEON processors (Nacona/Irwindale)	
Speed	2.80, 3.0, 3.20, 3.40, and 3.60 GHz	
System Memory		
Amount Installed	8 GB	
Memory Type	DDR2 400 (4 DIMMs, ECC)	
Power Management		
ACPI Sleep States (S1, S2, S3, S4)	S1, S4	
Server Board Product		
System uses logo'd motherboard	NO (Server boards are NOT eligible for logo under the Microsoft* Motherboard logo program)	
Board AA #/Fab	301	
Board Manufacturer	Intel Corporation	
Board Model	Intel® Server Board SE7320EP2	
Northbridge* Chipset Manufacturer	Intel Corporation	
Northbridge Chipset Model	Intel E7320 Chipset	
Southbridge* Chipset Manufacturer	Intel Corporation	
Southbridge Chipset Model	Intel E7320 Chipset	
BIOS		
BIOS Manufacturer	AMI*	
BIOS Version	SE7320EP20.86B.P.01.00.0010.05042051148	
BIOS Date	5/4/05	
BIOS URL (For Updates)	htttp://support.intel.com/support/motherboards/server/SE7320EP2/	

Bus Types			
	Check all that Apply		Check all that Apply
PS/2		AGP*	
1394		PCCard* (16-bit)	
CF (Compact Flash)		CardBus* (32-bit)	
PCI	$\checkmark$	USB	
Mini-PCI		USB 2.0	$\checkmark$
AMR		InfiniBand*	
ACR		Bluetooth*	
COM (Serial)	<b>V</b>	PCI Express	$\checkmark$
Integrated Components		·	
	Check all that Apply		Check all that Apply
Audio		Display	$\square$
IDE	<b>V</b>	Networking	
SCSI		RAID	
Modem		Bluetooth*	

### **Onboard Integrated Devices and Drivers**

Data in this section reflects system configuration at the time of WLP submission. The latest drivers for the Intel® Server Board SE7320EP2 are available for download at:

ttp://support.intel.com/support/motherboards/server/SE7320EP2/

Technology	os	Version
LAN Marvell Yukoun 88E8050 Network Connection Supports 10/100/1000	Windows Server 2003	v. 8.25.1.3
<b>Display</b> ATI* Rage* XL SVGA PCI video controller with 8 MB of video memory	Windows Server 2003	Embedded
Serial RAID ATA (Off the Hance Rapids) The Intel SATA system contains two independent SATA signal ports that can be configured as either a RAID 1 or 0	Windows Server 2003	v. 4.2.0318.2005

### **Product Data for HCL: Completion of WLP**

Data in this section reflects product data for HCL at time of WLP submission.

Product Data		
Product Name	Intel® Server Board SE7320EP2	
Additional Product Names		
Supported Platforms		
	Check Tested	Comments
Windows 2000 Server	$\checkmark$	
Windows 2000 Advanced Server	<b>V</b>	
Windows Server 2003, Web Edition	<b>V</b>	
Windows Server 2003, Standard Edition	<b>V</b>	
Windows Server 2003, Enterprise Edition	<b>V</b>	

# **Hardware Compatibility Tests Used**

Microsoft\* Windows Hardware Driver Central Server Testing Home Page: <a href="http://www.microsoft.com/whdc/hwtest/system/default.mspx">http://www.microsoft.com/whdc/hwtest/system/default.mspx</a>.

Please check this website regularly for test kit updates.

Operating Systems	Notes	Hardware Compatibility Tests (HCT)
Windows* 2000	HCT 9.502 Test Procedures for Systems, Servers and Cluster Servers (Windows 2000)	HCT 9.502 Test Kit (Windows 2000) (35.4 MB)
	http://download.microsoft.com/download/whistler/ Docs/Docs/W982KMeXP/EN- US/HCT9502_Systems.exe	http://download.microsoft.com/download/whistler/Tools/Tools/W98NT42KMeXP/EN-US/HCT9502UPD.EXE
	Logo'd Components Index Full Install	Logo'd Components Index Full Install (~9.8 MB)
		http://download.microsoft.com/download/whistler/Instal I/20.0/W982KMeXP/EN-US/logoidx.exe
	391 NDIS Intermediate Drivers Instructions	Beta NDIS Test Update (ndt391.exe) (2MB)
	http://download.microsoft.com/download/whistler/ Install/20.1/W982KMeXP/EN- US/NDISIntermedDriver.exe	http://download.microsoft.com/download/whistler/Instal I/12.2/W982KMeXP/EN-US/ndt391.exe
	386 NDIS Intermediate Drivers Instructions	NDIS Test Update for Windows 98 SE, Windows Me, and Windows 2000 (ndt386.exe) (2.02MB)
	http://download.microsoft.com/download/whistler/ Install/20.1/W982KMeXP/EN- US/NDISIntermedDriver.exe	http://download.microsoft.com/download/whistler/Instal l/12.2/W982KMeXP/EN-US/ndt386.exe
Windows Server 2003	HCT 11.2 Test Procedures and Readme files for Windows XP SP1 and Windows Server 2003 (4.95MB)	HCT 11.2 (Windows XP SP1 and Windows Server 2003) Test Kit (4.95MB)
	http://www.microsoft.com/whdc/hwtest/search/de tails.aspx?ID=725	http://www.microsoft.com/whdc/hwtest/search/details.a spx?ID=724
	Logo'd Components Index Full Install	Logo'd Components Index Full Install (~9.8 MB)
		http://download.microsoft.com/download/whistler/Instal I/20.0/W982KMeXP/EN-US/logoidx.exe

## **Errata and Contingencies**

Microsoft\*System HCT Errata list is available at:

http://www.microsoft.com/whdc/hwtest/search/results.aspx?type=errata&key=system&kit=-1

Operating System	Identification Number	Title
Windows* 2000	298	PCI Power Management Register Interface Test: False Failure
Windows 2000	372	ACPI System test fails systems that support ACPI table version 1.0 or greater
Windows Server 2003	610	Intel ICHx Contingency
Windows 2000	702	Audio tests are not required for servers that do not implement audio devices
Windows 2000	719	DVD test cannot be run on systems without a DVD drive
Windows 2000	722	PCI 2.2 Compliance test and PCI 2.1 (Cards) test might fail test systems with ATA/ATAPI controllers
Windows Server 2003	772	LAN Device Wake test is not required on network devices in mobile systems, multifunction, broadband, LAN emulation, wireless LAN, server LAN, or bus-powered USB network devices
Windows 2000	826	PCI 2.1 Compliance test, PCI 2.1 Cards test, PCI 2.2 Compliance test, and CardBus Bridge Register test fail on devices that are PCI 2.3-compliant
Windows Server 2003	860	Enable/Disable – Device I/O test fails on USB 2.0 host controllers
Windows Server 2003	901	The ACPI Verifier test fails the E820 table when the system memory controller is a child of the PCI Bus
Windows Server 2003	1012	Enable/Disable - Device I/O test false-fails because of LPT port errors
Windows 2000	1182	ACPI Sleep test conflicts with Windows 2000 Service Pack 4

#### **Submission Readme File**

Effective May 1, 2002, the new Microsoft standardized Readme form will be required for all hardware submissions that include any of the following testing exceptions:

- Test failures
- Tests not run
- Missing test logs
- Inconclusive test results

All testing exceptions must be identified with a valid Errata ID, Incident ID, or Contingency ID provided by WHQL. The new Microsoft standardized Readme file is available for download at: <a href="http://download.microsoft.com/download/whistler/install/1.0/w98nt42kmexp/en-us/readme.exe">http://download.microsoft.com/download/whistler/install/1.0/w98nt42kmexp/en-us/readme.exe</a>

# Testing Exceptions for Intel® Server SE7320EP2 Windows 2000 Submission

Data in this section reflects product data and test exceptions listed in section 2 of the Intel® Server SE7320EP2 Readme file at time of WLP First-Time submission ID Number 994359.

Windows 2000 testing no longer required when submitted with a current OS such as Windows 2003 Enterprise Edition.

#### Testing Exceptions for Intel® Server SE7320EP2 Windows Server 2003

Data in this section reflects product data and test exceptions listed in section 2 of the Intel® Server SE7320EP2 Readme file at time of WLP First-Time submission ID Number 994359.

Operating system (Windows XP, Windows 2000, etc.)	Failure type (Contingency, Errata, Incident)	ID number	
Windows 2003 Enterprise Edition 64 Bit	Errata	772	
Failing test name	Wake Device Server('Server-side Test')		
Applicable error message (Type N/A if the error message or failing text is excessive or if there is no text)			
Additional information (for example, test system in a multiple system configuration)	Both onboard NICs are gigabit		

#### Tip Additional Information

No additional information entered in section 3 of the Intel® Server SE7320EP2 Readme file at time of WLP submission ID 994359.

# **Appendix A – Submission History**

Microsoft "Designed for Windows\*" logo submission history for the Intel® Server SE7320EP2:

Submission ID	Туре	Date	OS Qualified	Processor Speeds	Board Revision	BIOS Version
994359	First-Time	6/27/05	Windows 2003 EE Windows 2000 as "Supported" only	2.80, 3.0, 3.20, 3.40, and 3.60 GHz	301	P01 5/04/05