



This Technical Advisory describes an issue which may or may not affect the customer's product

Intel Technical Advisory

TA-0845-1

5200 NE Elam Young Parkway
Hillsboro, OR 97124

October 23, 2006

System Software Updates Require Special Attention on Intel® 5000 Series Chipsets Server Boards

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice. Current characterized errata are available on request.

Products Affected

All Intel® 5000 Series Chipset Server Boards.

Description

As support for the Quad-Core Intel® Xeon® Processor 5300 series is added to the Intel BIOS, firmware and FRUSDR software, upgrades must occur in a certain order to ensure a valid system stack. .

Root Cause

Quad core detection and management requires SMBIOS Table 2.5 and more complex FRUSDRs. An update to BIOS 66 is required to obtain this Table. Tools which update FRUSDRs prior to BIOS update or update both at the same time will still require BIOS 66 be on the server prior to FRUSDR updates.

Corrective Action / Resolution

All Intel® 5000 Series Chipset Server Boards must be updated to BIOS 66 before attempting to update to FRUSDR packages supporting the Quad-Core Intel® Xeon® Processor 5300 series.

There are multiple tools and update packs provided to accomplish this task.

1. Use any of the following tools and packages to update from BIOS versions prior to BIOS 66.
 - the tools and software updates provided in the DOS Update Package containing BIOS 66
 - Intel® Deployment Assistant 1.0 or 1.1 on the Intel® Resource Toolkit 2 CD and the OFU/Intel® Deployment Assistant software update package containing BIOS 66
 - Intel® One-boot Flash Update (OFU) found on the Intel® System Management Software CD and the OFU/Intel® Deployment Assistant software update package containing BIOS 66.
2. After updating to BIOS 66, use the appropriate DOS FRUSDR package dated after October 15, 2006 to update to the FRUSDRs that include support for the Quad-Core Intel® Xeon® Processor 5300 series.
3. For future updates, you will be able to use any of :
 - Tools and software updates provided in the DOS Update Package
 - Intel® Deployment Assistant 1.2 (to be posted to <http://support.intel.com> by the end of November 2006)
 - OFU version located on <http://support.intel.com> dated after October 15, 2006.

Additional Information

Intel® One-boot Flash Update allows updating of the BIOS/BMC/and FRUSDRs from within Microsoft* Windows* Server 2003 or Red Hat* Enterprise Linux* 4.0. Version 9.6.1 or later should be used and will be available from <http://downloadfinder.intel.com> (search for OFU or look under your Server Board).

Intel® Deployment Assistant v1.0 or 1.1 is available by booting to the Intel® Server Resource CD 2 included in your boxed Server Board or from <http://downloadfinder.intel.com> (look under your Server Board using the OS selection of "OS independent"). After the BIOS 66 update, Intel® Deployment Assistant 1.2 should be used and will be available from the same support site. This will be an ISO download which should be made into a bootable CD to replace the CD that shipped with the boxed Intel® Server board.

Please contact your Intel Sales Representative if you require more specific information about this issue.

Enterprise Platforms & Services Division
Intel Corporation