



## Installing Windows NT 4.0 (Clean) on a Ultra100 Controller Card

### -Setup Procedure

- 1.) We **STRONGLY RECOMMEND** that you create a **Dos Partition (no larger than 4 GB in size)** before installing Windows NT 4.0 with our **Promise Ultra66 Controller card**. If possible boot up with a real dos boot disk, then execute [Microsoft's FDISK](#) to partition and format the hard disk drive. This will help to eliminate potential problems during the setup process.
- 2.) Being the Installation process by booting up the computer with CD ROM support. Change to the CD ROM Drive letter (yours may vary) by typing "D:" (without quotations) and then pressing "**enter**". Then type "**cd I386**" and then press the "**enter**" key. Next type (without quotations) "**winnt**" or "**winnt /x**" (if you already have the 3 startup diskettes. After the file copying process is complete, restart your computer with the **NT 4.0 boot diskette** labeled "**Disk1 Setup Boot disk**" when prompted.
- 3.) Proceed with the setup process until your reach the "**Mass Storage Controller auto detect screen**".
- 4.) Next a screen will appear showing a list of **Mass Storage Devices (IDE Controllers, SCSI cards, Etc.)** that have been recognized by the setup program. Press the "**S**" key to specify additional Mass Storage Controllers.
- 5.) When you reach the next screen, "**Other (Requires disk provided by a hardware manufacture)**" will already be selected on the bottom half of the setup screen. Press the "**enter**" key to continue.
- 6.) You will now be prompted to "**Please insert the disk labeled manufacture supplied support disk**". Insert our "**Promise Ultra100 Controller**" diskette and then press the "**enter**" key when ready.
- 7.) The device selection box appears with the "**Promise Ultra100 Controller**" already selected. Press the "**enter**" key.
- 8.) Now setup should display the following: "Setup has recognized the following Mass Storage Controller devices in your computer", "**Promise Ultra100 Controller**". Press the "**enter**" key to accept.
- 9.) Setup will now prompt you to "**Please insert the disk label Windows NT Setup Disk #3 in Drive A**". Press the "**enter**" key when ready to proceed.

10.) Continue on with the setup process until you reach the screen that prompts you to **select** a partition in which Windows NT will be **installed**. Select the **DOS PARTITION (formatted in FAT16)** that you created at the beginning of this setup procedure. Press the "**enter**" key to continue on with the NT setup process.

11.) After you choose a installation directory setup will examine your Hard Disk drive/s. Once the examination of the hard drive/s is complete, setup will ask for the "**Promise Ultra100 NT Driver Diskette**". Insert the diskette and then press the "**enter**" key. Setup will begin copying the driver files needed for your **Promise Ultra100 Controller**. When the copying process is complete you will see a message, "**This portion of the setup has completed successfully, remove floppy disk and reboot**".

12.) You have just finished the sections of the setup program that were **necessary** for the **proper** installation of your **Promise Ultra100 Controller** card. Complete the remainder of the setup process when your computer reboots.