

Legacy Software

The following outlines where the new management software will replace the legacy management software as these legacy tools will no longer be updated.

For those who have standardized on any of these legacy management products, they are still available via the web at www.hp.com/products/UPS under the software section.

HP UPS/CMC Supported Application Matrix							
Current Software		Legacy Software					
HP PM 3.1	HP RPM 1.0	HP PM 3.0	Power Manager Pro UPS	CPM 1.81	CIRM Lite	OnliNet 4.03	Lansafe III 4.17c
Shipping Products							
Pro UPS 500	•	∥	•	•	∥	∥	∥
T700*	•	•	•	∥	•	∥	•
T1000 XR	•	•	•	∥	•	∥	•
T1500 XR	•	•	•	∥	•	∥	•
T2200 XR	•	•	•	∥	•	∥	•
R1500 XR	•	•	•	∥	•	∥	•
R3000 XR	•	•	•	∥	•	∥	•
R5500 XR	•	•	•	∥	∥	∥	∥
R12000 XR	•	•	•	∥	∥	∥	•
CMC	∥	•	∥	∥	∥	•	∥
Legacy Products							
T700 Legacy	∥	∥	∥	∥	•	∥	•
T1000	∥	∥	∥	∥	•	∥	•
T1500	∥	∥	∥	∥	•	∥	•
T2000	∥	∥	∥	∥	•	∥	•
T2400	∥	∥	∥	∥	•	∥	•
R1500	∥	∥	∥	∥	•	∥	•
R3000	∥	∥	∥	∥	•	∥	•
R6000	•	•	•	∥	•	∥	•

HP Power Management Software OS Matrix							
Current Software		Legacy Software					
HP PM 3.1	HP RPM 1.0	HP PM 3.0	Power Manager Pro UPS	CPM 1.81	CIRM Lite	OnliNet 4.03	Lansafe III 4.17c
Novell NetWare 5.1	•	•	•	•	∥	∥	•
Novell NetWare 6	•	•	•	∥	∥	∥	∥
Red Hat Linux 7.3	•	•	•	∥	∥	∥	∥
Red Hat Linux 8.0	•	•	•	∥	∥	∥	∥
Red Hat Ent. Server 2.1	•	•	∥	∥	∥	∥	∥
Red Hat Ent Server 3.0	•	∥	∥	∥	∥	∥	∥
United Linux 1.0	∥	•	∥	∥	∥	∥	∥

Windows 2000	•	•	•	•	•	•	•
Windows Server 2003	•	⌘	⌘	⌘	⌘	⌘	⌘
Windows NT 4.0	•	•	•	•	•	•	•

Legend

•	Supported
⌘	Not supported
*	Models 204015-001, 204015-291, 204015-B31 only