

 <p style="text-align: center;"><b>FIC Products with CPU &amp; BIOS Status</b></p> <p><b>Socket 478 based board :</b></p>						
<b>Model Name</b>			<b>VI35VL</b>			
<b>PCB Version</b>			<b>1.3</b>			
<b>BIOS Version</b>			<b>SAQ41</b>			
<b>Flash Utility</b>			<b>Flash820A</b>			
<b>Intel : (Celeron/L2 Cache 128KB)</b>						
Celeron 1.7 GHz	FC-PGA2	100x17	v			
Celeron 1.8 GHz	FC-PGA2	100x18	v			
Celeron 1.9 GHz	FC-PGA2	100x19	v			
Celeron 2.0 GHz	FC-PGA2	100x20	v			
Celeron 2.2 GHz	FC-PGA2	100x22	v			
Celeron 2.4 GHz	FC-PGA2	100x24	v			
<b>Intel : (Willamette/L2 Cache 256KB)</b>						
Pentium 4 1.4 GHz	FC-PGA2	100x14	v			
Pentium 4 1.5 GHz	FC-PGA2	100x15	v			
Pentium 4 1.6 GHz	FC-PGA2	100x16	v			
Pentium 4 1.7 GHz	FC-PGA2	100x17	v			
Pentium 4 1.8 GHz	FC-PGA2	100x18	v			
Pentium 4 1.9 GHz	FC-PGA2	100x19	v			
Pentium 4 2.0 GHz	FC-PGA2	100x20	v			
<b>Intel : (Northwood/L2 Cache 512KB)</b>						
Pentium 4 1.6GHz	FC-PGA2	100x16	v			
Pentium 4 1.73GHz	FC-PGA2	133x13	v			
Pentium 4 1.8GHz	FC-PGA2	100x18	v			
Pentium 4 2.0GHz	FC-PGA2	100x20	v			
Pentium 4 2.2GHz	FC-PGA2	100x22	v			
Pentium 4 2.26GHz	FC-PGA2	133x17	v			
Pentium 4 2.4GHz	FC-PGA2	100x24	v			
Pentium 4 2.4GHz	FC-PGA2	133x18	v			
Pentium 4 2.50GHz	FC-PGA2	100x25	v			
Pentium 4 2.53GHz	FC-PGA2	133x19	v			
Pentium 4 2.66GHz	FC-PGA2	133x20	v			
Pentium 4 2.8GHz	FC-PGA2	133x21	v			
Pentium 4 3.06GHz	FC-PGA2	133x23				
<b>Remark: V...Support</b>						