

HP SmartStart Scripting Toolkit Linux and Windows Editions

Support Matrix

Overview

The Linux and Microsoft® Windows® editions of the HP SmartStart Scripting Toolkit provide a collection of tools that assist with configuring HP ProLiant server hardware and installing your operating system.

Hardware support

HP SmartStart Scripting Toolkit supports the following servers. All Toolkit utilities except CONREP can run on unsupported servers, but the utilities have been tested only on the listed servers.

NOTE: The following controllers are not supported by the SmartStart Scripting Toolkit and must be configured manually:

- HP 8 Internal Port SAS HBA with RAID
- HP 6-Port SATA RAID controllers in the HP ProLiant ML310 G2, ML310 G3, and ML350 G4p Servers
- Embedded LSI ATA RAID controllers in the HP ProLiant DL320 G2, ML330 G2, ML310, and ML330 G3 Servers
- Embedded SATA RAID controllers in the HP ProLiant DL320 G3, DL320 G4, ML310 G2, ML310 G3 Servers

ProLiant BL servers	ProLiant DL servers	ProLiant ML servers
ProLiant BL40p	ProLiant DL360 G3	ProLiant ML310 G5
ProLiant BL45p	ProLiant DL360 G4	ProLiant ML310 G5p
ProLiant BL45p G2	ProLiant DL360 G4p	ProLiant ML350 G3
ProLiant BL260c G5	ProLiant DL360 G5	ProLiant ML350 G4
ProLiant BL460c	ProLiant DL360 G6	ProLiant ML350 G4p
ProLiant BL460c G5	ProLiant DL365	ProLiant ML350 G5
ProLiant BL460c G6	ProLiant DL365 G5	ProLiant ML350 G6
ProLiant BL465c	ProLiant DL380 G3	ProLiant ML370 G3
ProLiant BL465c G5	ProLiant DL380 G4	ProLiant ML370 G4
ProLiant BL480c	ProLiant DL380 G6	ProLiant ML370 G5
ProLiant BL490c G6	ProLiant DL380 G5	ProLiant ML370 G6
ProLiant BL495c G5	ProLiant DL385	ProLiant ML530 G2
ProLiant BL680c G5	ProLiant DL385 G2	ProLiant ML570 G2
ProLiant BL685c	ProLiant DL385 G5	ProLiant ML570 G3
ProLiant BL685c G5	ProLiant DL385 G5p	ProLiant ML570 G4
ProLiant BL685c G6	ProLiant DL560	—
ProLiant BL2x220c G5	ProLiant DL580 G2	—
—	ProLiant DL580 G3	—
—	ProLiant DL580 G4	—
—	ProLiant DL580 G5	—
—	ProLiant DL585 G2	—
—	ProLiant DL585 G5	—
—	ProLiant DL760 G2	—
—	ProLiant DL785 G5	—

HP recommends downloading the latest Lights-Out firmware for your server. The Linux and Microsoft® Windows® editions of the SmartStart Scripting Toolkit support the following Lights-Out options.

Lights-Out option	Firmware version
Remote Insight Lights-Out Edition II	1.13 or later
Integrated Lights-Out	1.41 or later
Integrated Lights-Out 2	1.00 or later

ProLiant BL servers	ProLiant DL servers	ProLiant ML servers
ProLiant BL20p G2	ProLiant DL160 G6	ProLiant ML110 G5
ProLiant BL20p G3	ProLiant DL180 G6	ProLiant ML115 G5
ProLiant BL20p G4	ProLiant DL320 G2	ProLiant ML150 G6
ProLiant BL25p	ProLiant DL320 G3	ProLiant ML310
ProLiant BL25p G2	ProLiant DL320 G4	ProLiant ML310 G2
ProLiant BL30p	ProLiant DL320 G5	ProLiant ML310 G3
ProLiant BL35p	ProLiant DL320s	ProLiant ML310 G4

© Copyright 2004, 2009 Hewlett-Packard Development Company, L.P.

The information contained herein is subject to change without notice. The only warranties for HP products and services are set forth in the express warranty statements accompanying such products and services. Nothing herein should be construed as constituting an additional warranty. HP shall not be liable for technical or editorial errors or omissions contained herein.

Confidential computer software. Valid license from HP required for possession, use or copying. Consistent with FAR 12.211 and 12.212, Commercial Computer Software, Computer Software Documentation, and Technical Data for Commercial Items are licensed to the U.S. Government under vendor's standard commercial license.

Microsoft and Windows are U.S. registered trademarks of Microsoft Corporation.

March 2009 (Eleventh Edition)
Part Number 365442-403



365442-403

Printed in the US

Printed in the US