Important!

The latest software is the [HD6A269727V1E]. Please use this software to update from older version.

The [Ver02C] should be used only when "FREEZE" problem occurred. Please do not use this unless "FREEZE" problem is caused.

[HD6A269727V1E] : For normal update. [Ver02C] : Only for FREEZE problem solution.

MDR515H